Submit 1 Copy Office	To Appropriate District	State of New Mexico					Form C-103			
District I - (575		Energy, Minerals and Natural Resources					Revised July 18, 2013 WELL API NO.			
District II - (57	1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283  811 S. First St. Artesia NM 88210  OIL CONSERVATION DIVISION						30-025-34946			
	811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178  1220 South St. Francis Dr.						5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505						``	STATE FEE X  6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM						19552		rease 110.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS							7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							South Hobbs Unit (G/SA)			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							8. Well Number 239			
Type of Well: Oil Well    Gas Well    Other Injector      Name of Operator							9. OGRID Number			
Occidental Permian Ltd							157984			
3. Address of Operator JUL 2 8 2016							10. Pool name or Wildcat			
P.O. Box 4294, Houston, TX 77210							Hobbs (G/SA)			
4. Well Loc	ation t Letter   :	1984	feet from the	South	EIV	ine and	370	feet from t	he East	line
	tion 5		Township	19S Ra		38E	NMPM	_	County	Lea
		11. Elevat	tion (Show wh							
		3624' K	В							
	12 Charle A		a Day to In	diasta M	atuma (	f Matica 1	Damont o	. Other De	ata	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data										
NOTICE OF INTENTION TO: SUBSEQUENT REPORT (								ORT OF:		
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORI									LTERING CA	ASING
TEMPORARILY ABANDON							NS. 🔲 P	AND A		
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   DOWNHOLE COMMINGLE										
	OOP SYSTEM									
OTHER:					OTHE					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE BUILE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of										
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.										
MIRU x NDWH x NUBOP										
Release inj. pkr x POOH 128 jts										
RIH 5 ½" CIBP@ 4076'										
	Perf'd 88 shot @ 4		60'							
RIH pkr @ 4020' x RIH 123 jts.										
•	Ran acid job w/ 32									
•	RIH 124 jts x on/o									
•	Reset pkr @ 3985									
•	Ran MIT – chart a									
•	RD x NDBOP x NU	WH								
			$\neg$						1	
Spud Date:	06/03/16		Rig R	telease Da	te:	06/08/16				
			_						J	
T1 1:		1	1 1 . 4	- 4 - 41 - 1 -	-1 - C	1 1 1	11.1	C		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.										
SIGNATURE	april	Hax	TITL	E Regulat	ory Cod	ordinator		DATE	E07/26/2	016
Type or print	name April Hood		E-ma	ail address	: April	_Hood@Oxy	.com	PHON	NE: 713-36	6-5771
For State Use Only										
APPROVED BY: V Welly & New And Sit Superusular 8/8/206										
APPROVED BY: TITLE Conditions of Approval (if any):										

