

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04704
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Apache Corp.		6. State Oil & Gas Lease No. BO-1511-0006
3. Address of Operator P O box Drawer D Monument NM 88265		7. Lease Name or Unit Agreement Name State F DE
4. Well Location Unit Letter <u>M</u> : <u>330</u> feet from the <u>S</u> line and <u>330</u> feet from the <u>W</u> line Section <u>19</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County		8. Well Number 004
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3636		9. OGRID Number 873
		10. Pool name or Wildcat Eumont Yates 7RQ (gas)76480

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 3343-3868

1. MIRU. NU-BOP. POOH W/ TBG.
2. SET CIBP @ 3268. DUMP BAIL 35'CMT ON CIBP.
3. LOAD CSG W/ PKR FLUID. TEST TO 550#.
4. LD TBG. NOTIFY OCD 24 HRS BEFORE TESTING & CHART RECORD.
5. REQUEST TA STATUS.

Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart

Rule 19.15.25.14

Set CIBP, RBP or Packer within 100 feet of uppermost
perfs or open hole Pressure test to 500 psi for 30 minutes with
a pressure drop of not greater than 10% over a
30 minute period

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Sisk TITLE SR PUMPER DATE 8/16/2016

Type or print name JOEL SISK E-mail address: joel.sisk@apacheccorp.com PHONE: 575-441-0793

For State Use Only

APPROVED BY: Maury Brown TITLE Dist Supervisor DATE 8/16/2016

Conditions of Approval (if any):