## Form 3160 HOBE 3 OCD

UNITED STATES

DEPARTMENT OF THE INTERIOR

SEP 1 2 SUREAU OF LAND MANAGEMENT

### NMOCD Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.	NM0177517	
6. If Indian, Allottee	e or Tribe Name	

SUNDRY NOTICES AND REPORTS ON WELLS

TO Live this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

abandoned well.	Use Form 3160-3 (A	PD) for such proposals	) <u>.</u>	di n
SUBMIT IN	TRIPLICATE - Other instr	uctions on page 2	7. If Unit of CA/Agr Cato San Andres	reement, Name and/or No.
✓ Oil Well Gas Well Other		8. Well Name and N	8. Well Name and No. Cato San Andres Unit #106 ✓	
2. Name of Operator Cano Petro of N	lew Mexico		9. API Well No. 300	0520056
3a. Address 823 S Detroit Ave Suite	300	3b. Phone No. (include area code (918) 582-0088	(2) 10. Field and Pool of Cato San Andres	
4. Location of Well (Footage, Sec., T., F NWSW, Sec 15, 8S, 30E	R.,M., or Survey Description) 980 FSL 660 FWL	/	11. Country or Parisi Chaves Co, NM	h, State
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTICE, REPORT OR OT	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
✓ Notice of Intent	Acidize Alter Casing	Deepen Hydraulic Fracturing	Production (Start/Resume	) Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other .
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
13. Describe Proposed or Completed O		ertinent details, including estimated		vor and approximate duration thereof. If

3. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

The 3 phase power line running from #91 to #106 was disconnected and de-energized by an electrician on 07/06/2016 due to an electrical problem. Well #106 has not been operating since then. Requesting permission for Temporarily Abandoned status at this time.

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

Power Must Be Safely Restored To Well Either By Running The Power Line On Power Poles Or Below The Surface Or Well Must Be Temporarily Abandoned Per The Attached Temporary Abandonment Of Wells On Federal Lands Conditions Of Approval By NOV 30 2016!

4. I hereby certify that the foregoing is true and correct. Name (Printed Typed)		
Richard Hierold	To	
Signature	8/18/16	
THE SPACE FOR FEDERA	AL OR STATE OFICE USE	
/S/ DAVID R. GLASS	PETROLEUM ENGINEER	AUG 3 0 2016
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

APPROVED FOR 3 MONTH PERIOD NOW 3 Q 2016

MAB/OCD 9/15/2016

#### BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)