Office Day of National Description	Form C-103
District 1 = (575) 393-6161 Energy, winerals and Natural Resources	Revised August 1, 2011
State of New Mexico Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OCT 0 30114 CONSERVATION DIVISION	30-025-07613
District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 8705 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	b. State Off & Gas Lease 110.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injector	8. Well Number: 30
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter H: 1980 feet from the North line and 660	_feet from theEastline
Section 5 Township 19S Range 38E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3610' (GL)	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. One of Appropriate Don to Maleure Material of Maleure	report of Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	RK ALTERING CASING
TEMPORARILY ABANDON	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE	
OTHER: OAP/AT OTHER:	
	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	empletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POON with injurious analysis and proposed completion of recompletion.	procedure we plan to use
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL the closed-	procedure we plan to use
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations tank and ha	procedure we plan to use
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF dienocal perforations	procedure we plan to use oop system with a steel oul contents to the required
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid During this the closed-lank and had disposal perforations	procedure we plan to use
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825'	procedure we plan to use oop system with a steel oul contents to the required
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT Cond	procedure we plan to use oop system with a steel oul contents to the required
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use oop system with a steel oul contents to the required r ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use coop system with a steel contents to the required r ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use soop system with a steel sul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use oop system with a steel oul contents to the required r ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use soop system with a steel sul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond OCI	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify O Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify O Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond OCI	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify O Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU. ND BOP. NU Wellhead. Cond OCI	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify O Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU, ND BOP, NU Wellhead. Cond OCI Spud Date: Rig Release Date: Prior of I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Production Engineer	procedure we plan to use oop system with a steel aul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief. DATE 10/03/2016
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU, ND BOP, NU Wellhead. Cond OCI Spud Date: Rig Release Date: Prior of I hereby certify that the information above is true and complete to the best of my knowledged and the complete to the com	procedure we plan to use soop system with a steel sul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'*-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU, ND BOP, NU Wellhead. Cond OCI Spud Date: Rig Release Date: Prior of I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Production Engineer	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours running MIT Test & Chart DATE 10/03/2016 PHONE: 713-497-2053
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU, ND BOP, NU Wellhead. Cond OCI Spud Date: Rig Release Date: Prior of Thereby certify that the information above is true and complete to the best of my knowledged and the complete to the best of my knowledged signature. TITLE Production Engineer Type or print name Jacob S. Cox E-mail address: Jacob Cox @oxy.com For State Use Only	procedure we plan to use cop system with a steel cul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours running MIT Test & Chart DATE 10/03/2016 PHONE: 713-497-2053
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1. MIRU PU. ND Wellhead. NU BOP 2. POOH with injection equipment 3. Run CBL 4. PB existing perforations 5. Perforate in San Andres formation from 4005'-35' at 6 SPF 6. AT with 2500 gal 15% NEFE acid 7. RIH with injection equipment. PKR SA 3825' 8. Perform MIT 9. RDPU, ND BOP, NU Wellhead. Cond OCI Spud Date: Rig Release Date: Prior of I hereby certify that the information above is true and complete to the best of my knowledged and the complete to the com	procedure we plan to use oop system with a steel aul contents to the required r ODC Rule 19.15.17 ition of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief. DATE 10/03/2016