

10/5/2014

Plugging Report TLSAU #75

9/8/2016 Cleared road and location. Moved in rig and rigged up. Dug out cellar. There was no surface head. Just a clamp on the 4 ½" casing and open 8 5/8" casing. Installed BOP. No pipe in the well. Moved pipe and remaining equipment from the #87 well. RIH with pipe. Casing started running over on second joint. Tagged existing CIBP at 2532'. SION.

9/12/2016 Haul fresh and brine to location. Circulated MLF and tested casing to 500#. Spotted 45 sx Class C on top of CIBP and POOH with tubing.

9/13/2016 RIH and tagged cement at 1887'. Perforated 4 ½" casing at 1000'. RIH with 4 ½" AD-1 packer and pressured up on perfs to 500#. Bled to 350# in 5 minutes. Repeated the process with same result. POOH with packer and RIH open ended to 1052' and spotted 25 sx cement with CaCl. POOH loaded casing and pressured up to 500# and shut in. WOC and tagged cement at 812'. Perforated 4 ½" casing at 100' and established circulation. Pumped cement down 4 ½" casing to perfs at 100' and up annulus to surface. Took 35 sx. Rigged down. Cut off wellhead and cement was to surface on both strings. Installed marker and cut off anchors. Cleared location and cleaned the pit.