Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-025-35556
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 HOBB Soft CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Eronois Dr	STATE STATE
$\frac{1220 \text{ South St. Planets Dr.}}{1220 \text{ South St. Planets Dr.}}$ $\frac{1220 \text{ South St. Planets Dr.}}{1220 \text{ South St. Planets Dr.}}$	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State A A/C 1
1. Type of Well: Oil Well 🗌 Gas Well 🖾 Other WIW	8. Well Number
2. Name of Operator	9. OGRID Number
Merit Energy Company	14591
3. Address of Operator	10. Pool name or Wildcat
13727 Noel Rd. Ste. 1200, Dallas, TX 75240	Jalmat; Tansill; Yates; 7 Rivers
4. Well Location	
Unit Letter I :1980feet from theSouth line and	660 feet from the East line \checkmark
Section 9 Township 23S Range 36E NMP	M County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3431' GR	
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTE'	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PI INT TO PA REMEDIAL WO	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER. ()THER.	
OTHER:OTHER:OTHER:	nd give pertinent dates including estimated dat
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Complete Action 2019. 	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Complete Action 2010 (2010) 	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Complete Action 2019. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 	ompletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 	ompletions: Attach wellbore diagram of () 1350' sqz 35 sxs to 1250' Tag (@ 1236'.
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 	ompletions: Attach wellbore diagram of () 1350' sqz 35 sxs to 1250' Tag (@ 1236'.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 	ompletions: Attach wellbore diagram of () 1350' sqz 35 sxs to 1250' Tag (@ 1236'.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ 	ompletions: Attach wellbore diagram of () 1350' sqz 35 sxs to 1250' Tag (@ 1236'.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. 	ompletions: Attach wellbore diagram of (2) 1350' sqz 35 sxs to 1250' Tag (2) 1236'. 738' to 343' Tag (2) 484'. Perf (2) 100' circ 35
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 Approved for Plugging of well bond is retained pending rest of the C-103, Specific for SubWell Plugging, which may be web page under forms. I hereby certify that the information above is true and complete to the best of my knowled 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 lbore only. Liability under oration and completion sequent Report of found on the OCD lge and belief.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 Approved for Plugging of well bond is retained pending rest of the C-103, Specific for Sub-Well Plugging, which may be web page under forms. 	ompletions: Attach wellbore diagram of (2) 1350' sqz 35 sxs to 1250' Tag (2) 1236'. 738' to 343' Tag (2) 484'. Perf (2) 100' circ 35 lbore only. Liability under oration and completion sequent Report of found on the OCD lge and belief.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 Approved for Plugging of well bond is retained pending rest of the C-103, Specific for Subs Well Plugging, which may be twee page under forms. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	ompletions: Attach wellbore diagram of () 1350' sqz 35 sxs to 1250' Tag (() 1236'. 738' to 343' Tag (() 484'. Perf (() 100' circ 35) () 100' circ 35 ()
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 Approved for Plugging of well bond is retained pending rest of the C-103, Specific for Subs Well Plugging, which may be twee page under forms. I hereby certify that the information above is true and complete to the best of my knowled SIGNATUREChris Romero E-mail address: 	ompletions: Attach wellbore diagram of (a) 1350' sqz 35 sxs to 1250' Tag (a) 1236'. 738' to 343' Tag (a) 484'. Perf (a) 100' circ 35 Ibore only. Liability under oration and completion sequent Report of found on the OCD Ige and belief. DATE10/31/16 PHONE: _432-563-3355
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 9/26/16—MIRU, RIH tbg Tag existing CIBP 2 3040'. 9/27/16—Circ hole w/ MLF press test csg good, spot 30 sxs @ 3040' to 2737' perf @ 9/28/16—Perf @ 688' press up re-perf @ 688' press up, OCD ok'd to spot 40 sxs @ sxs to surface, cmt fell to 60' top off w/ 10 sxs cmt fell again. 9/29/16—TOC @ 12' top off w/ 5 sxs cmt RDMO. Spud Date: 5/15/01 Approved for Plugging of well bond is retained pending rest of the C-103, Specific for Subs Well Plugging, which may be twee page under forms. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	Ompletions: Attach wellbore diagram of (2) 1350' sqz 35 sxs to 1250' Tag (2) 1236'. 738' to 343' Tag (2) 484'. Perf (2) 100' circ 35 lbore only. Liability under oration and completion sequent Report of found on the OCD Ige and belief.