Submit 1 Copy To Appropriate District Office	State of item mexico		Form C-103
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
District II - (575) 748-1283         OIL CONSERVATION DIVISION           District III - (505) 334-6178         1220 South St. Francis Dr.		DIVISION	30-025-20029
		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505		STATE     FEE     ~       6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH /			7. Lease Name or Unit Agreement Name STATE CP
1. Type of Well: Oil Well Gas Well OtherOBBS OCD			8. Well Number
2. Name of Operator			9. OGRID Number
Devon Energy Production Company, LP NOV UO LOU			6137 10. Pool name or Wildcat
3. Address of Operator 333 W. Sheridan Avenue, Oklahor	na City, OK 73102 RECEN	VED	E-K;Yates-Seven Rivers-Queen
4. Well Location			
Unit Letter E :1654_feet from theNorth line and660feet from theWest line			
Section         1         Township         18S         Range         33E         NMPM         Lea         County, NM           11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR			
4106' KB; 4091' GL; 15' KB to GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT I			
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK			K 🛛 🖸 INT TO PA 👬 🦛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB P&A R
CLOSED-LOOP SYSTEM			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. MIRU. Retrieve rod pump and 2-3/8" production tubing assembly from 4,106'.			
<ol> <li>Circulate wellbore with 10# mud between plugs. Pressure test cs9</li> </ol>			
3. Set CIBP @ 4,090'. Tag plug. Spot 25 sx (360') Cl C @ 4,090' - 3,730'. (open perfs 4,120'-4,160')			
<ol> <li>Spot 30 sx (430') Cl C @ 3,170' - 2,740'. Tag TOC. (T.Yates @ 3,170'; B.Salt @ 2,868')</li> <li>Perf thru 4-1/2" &amp; 8-5/8" @ 1,720'. Pump 70 sx (150') Cl C in/out @ 1,720' - 1,570'. Tag TOC. (T.Salt @ 1,720')</li> </ol>			
6. Perf thru $4-1/2$ & $8-5/8$ " casing @ 370'. Pump 235 sx Cl C in/out to surface on $8-5/8$ " & $4-1/2$ " casings.			
7. Cut wellhead off BGL, Set dry hole marker.			
3' Verify Cement to surface all strings			
all strings			
NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS			
Spud Date:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Romie Slack TITLE Production Technologist DATE 11-3-16			
Type or print name Ronnie Slack E-mail address:Ronnie.Slack@dvn.com PHONE: _405-552-4615			
For State Use Only			
APPROVED BY: Maluhitale TITLE Petroleum Engr. Specialist DATE 11/8/2016 Conditions of Approval (if any):			
11 11 × 11 × 11 × 11 × 11 × 11 × 11 ×			



