

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36529
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cooper 8 (317136)
8. Well Number 2
9. OGRID Number 244835
10. Pool name or Wildcat Monument SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
J. Cooper Enterprises, Inc (244835)

3. Address of Operator
Box 55 Monument, NM 88265

4. Well Location
Unit Letter H : 1850 feet from the N line and 630 feet from the E line
Section 8 Township 20 Range 37 E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: Convert to SWD ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Convert to SWD per administrative order SWD 1613. Will convert to SWD as soon as supplement information to the order is approved.
(See attachment)

HOBBS OCD

NOV 17 2016

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eddie W. Seay TITLE Agent DATE 11/17/16

Type or print name Eddie W. Seay E-mail address: seay04@leaco.net PHONE: 575-392-2236

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 11/30/16

Conditions of Approval (if any):

**ATTACHMENT TO C-103
COOPER 8 #2 SWD
SWD 1613**

Work Plan for Conversion.

1. Notify OCD before any work begins.
2. Install new anchors and 5 1/2" x 8 5/8" wellhead.
3. Rig up unit, install BOP.
4. Drill out cement plugs down to 5060' , test casing.
5. Selectively perforate from 4300' to 4900' .
6. Acidize as needed.
7. Run 3 1/2" IPC tubing and 5 1/2" packer and set within 100 ft. of top perforations, approximately 4200' .
8. Load backside with packer fluid.
9. Notify OCD, run MIT.
10. Put on injection and file sundry notice.

HOBBS OCD
NOV 17 2016
RECEIVED