
	Form 3160-5       UNITED STATES         (*ugust 2007)       DEPARTMENT OF THE INTERIOR         BUREAU OF LAND MANAGEMENT       OCD Hobbs         SUNDRY NOTICES AND REPORTS ON WELLS         DEC       9 20 Po not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM12568A 6. If Indian, Allottee or Tribe Name			
:	RECENSION T IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
	1. Type of Well					8. Well Name and No. BONDURANT FEDERAL 007 ✓			
	2. Name of Operator ✓ Contact: DAVID A EYLER CIMAREX ENERGY CO OF COLORAE@Mail: DEYLER@MILAGRO-RES.COM					9. API Well 30-025			
				o. (include area code 37-3033	10. Field and Pool, or Exploratory BUFFALO (YATES)				
	4. Location of Well <sup>*</sup> (Footage, Sec., T., R., M., or Survey Description) Sec 1 T19S R32E SWNE 1650FNL 1900FEL √						y or Parish, and State COUNTY, NM		
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
	TYPE OF SUBMISSION	ON TYPE OF ACTION							_
	<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	<ul> <li>Acidize</li> <li>Alter Casing</li> <li>Casing Repair</li> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	□ Nev ⊠ Plu	epen cture Treat v Construction g and Abandon g Back	□ Reclam	plete rarily Aban	INT TO PA 🦄 🗶 P&A NR P&A R		
forf + Saz > Perf. Saz	<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)</li> <li>1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS.CMT. @ 3,450'-3,330'(T/YATES,B/SALT).</li> <li>2) CIRC. WELL W/ PXA MUD; PRES. TEST 5-1/2" CSG. TO 500# X HOLD.</li> <li>3) PUMP 35 SXS.CMT. @ 1,600'-1,375'(T/SALT, T/ANHY.); WOC X TAG CMT. PLUG.</li> <li>4) MIX X CIRC. TO SURF. 85 SXS.CMT. @ 660'-3.</li> <li>5) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL GROUND LEVEL DRY HOLE MARKER.</li> <li>DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.</li> </ul>								
	SEE ATTACHED FOR CONDITIONS OF APPROVAL								
	For CIMAREX ENERGY CO OF			ed by the BLM Well Information System COLORADO, sent to the Hobbs DEBORAH MCKINNEY on 09/01/2016 () Title AGENT					
	Signature (Electronic Submission)			Date 08/10/	2016				
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
(	Approved By			Title Er Office CF	ing D			Date	29/14
-	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								
** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **									



Cimarex Energy Co. of Colorado CIMAREX Bondurant Federal 7 API 30-025-31326 Property: 309563-032.01 1650' FNL & 1900' FEL Sec. 1. T-19-S. R-32-E. Lea Co. NM Ty Daws 3/30/11 Updated 6/23/2016 by S.Hanford T/ANHY~ 1,425' T/SALT ~ 1,550' B/SALT TI ANHY > 3,405' YATES CIRC. 85 SXS. CMT. @ 660'-3'. 8 5/8" 28# K55 csg @ 606' Cmt w/ 400 sx, cmt circ. PXA MUD Pump 35 5x5.cm7 @ 1,600-1,375-DAG Pump 25 SXS. CMT @ 3,450'-3,330 -SET 5 1/2" CIBP @ 3,450! Yates Perfs: (3484' - 3502') 2SPF 38 holes 5 1/2" 15.5# K55 csg @ 3740' Cmt w/ 1100 sx, cmt circ. PBTD @ 3680' TD @ 3740 DAE 08/10/16

Printed 8/10/2016

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the <b>BLM is to be contacted with justification to receive an extension for completing the cut off.** Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least <sup>1</sup>/<sub>4</sub> inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.** 

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>**Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u></u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted</u>**