HOBBS OCD	
Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240	Form C-103
Office District I	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 RECEIVEDCONSERVATION DIVISION	30-025-00350
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	STATE BH
1. Type of Well: Oil Well Gas Well 🛛 Other SWD	8. Well Number 1
2. Name of Operator	9. OGRID Number
DEVON ENERGY PRODUCTION CO LP 3. Address of Operator	6137 10. Pool name or Wildcat
PO BOX 250, ARTESIA, NM 88211	SWD; SAN ANDRES
4. Well Location	
Unit Letter P : 990 feet from the SOUTH line and 330 feet from the EAST	<u>line</u>
Section <u>32</u> Township <u>15S</u> Range <u>32E</u> NMPM County <u>LEA</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
4322' KB; 4309' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	Data
12. Check Appropriate Box to indicate Nature of Notice, Report of Other L	Jata
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER:	eady for OCD inspection after P&A
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Ope	eady for OCD inspection after P&A Pm prator's pit permit and closure plan.
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	eady for OCD inspection after P&A Pm prator's pit permit and closure plan. properly abandoned.
OTHER: □ Image: Location is related in compliance with OCD rules and the terms of the Ope Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been set in Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of the Ope Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of the Ope Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of te	eady for OCD inspection after P&A PM prator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: □ Image: Location is response to the open set of the open	eady for OCD inspection after P&A PM prator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: □ Image: Location is related in compliance with OCD rules and the terms of the Ope Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Image: Mathematical All pits have been remediated in compliance with OCD rules and the terms of the Ope Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been set in Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of the Ope Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of the Ope Image: Ope Image: Rat hole and terms of the Ope Image: Rat hole and terms of te	eady for OCD inspection after P&A PM prator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: □ ☑ Location is r ☑ All pits have been remediated in compliance with OCD rules and the terms of the Ope ☑ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been ☑ A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	eady for OCD inspection after P&A Pm prator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR
OTHER: □ ☑ Location is r ☑ All pits have been remediated in compliance with OCD rules and the terms of the Ope ☑ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been ☑ A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☑ The location has been leveled as nearly as possible to original ground contour and has other production equipment.	eady for OCD inspection after P&A PM rator's pit permit and closure plan. properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
OTHER: □ ☑ Location is r ☑ All pits have been remediated in compliance with OCD rules and the terms of the Ope ☑ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been ☑ A steel marker at least 4" in diameter and at least 4' above ground level has been set in ○ OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☑ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below group	eady for OCD inspection after P&A PM rator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.
 OTHER: 	eady for OCD inspection after P&A PM rator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with
 OTHER: ☐ Location is r All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☑ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below grou ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. 	eady for OCD inspection after P&A PM prator's pit permit and closure plan. properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed
OTHER: □ Image: Location is response to the openation of the openation openation openation openation openatis and	eady for OCD inspection after P&A M rator's pit permit and closure plan. properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed
 OTHER: ☐ Location is r All pits have been remediated in compliance with OCD rules and the terms of the Ope A at hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☑ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below group if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed.) 	eady for OCD inspection after P&A PM prator's pit permit and closure plan. properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed
 OTHER: ☐ Location is r All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. So The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. 	eady for OCD inspection after P&A Prator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. bave been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 OTHER: ☑ Location is r All pits have been remediated in compliance with OCD rules and the terms of the Ope ☑ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been ☑ A steel marker at least 4" in diameter and at least 4' above ground level has been set in <u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u> ☑ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below grou ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. 	eady for OCD inspection after P&A PM properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non-
 OTHER: Image: All pits have been remediated in compliance with OCD rules and the terms of the Open Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Rat hole and cellar have been filled and leveled. Cathodic protection holes have been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. Image: The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMACC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles are service poles. 	eady for OCD inspection after P&A PM properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non-
 OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Operator and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. 	eady for OCD inspection after P&A A A A A A A A A A A A A A A A A A A
 OTHER: Image: All pits have been remediated in compliance with OCD rules and the terms of the Open Rat hole and cellar have been filled and leveled. Cathodic protection holes have been Rat hole and cellar have been filled and leveled. Cathodic protection holes have been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. Image: The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMACC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles are service poles. 	eady for OCD inspection after P&A M rator's pit permit and closure plan. properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. bave been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well
OTHER: □ </td <td>eady for OCD inspection after P&A A A A A A A A A A A A A A A A A A A</td>	eady for OCD inspection after P&A A A A A A A A A A A A A A A A A A A
OTHER: □ </td <td>eady for OCD inspection after P&A A mator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c) All fluids have been removed from non- ind lines have been removed from lease and well hedule an inspection. DPPORTDATE11/29/2016</td>	eady for OCD inspection after P&A A mator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c) All fluids have been removed from non- ind lines have been removed from lease and well hedule an inspection. DPPORTDATE11/29/2016
OTHER: □ </td <td>eady for OCD inspection after P&A Protor's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ind lines have been removed from lease and well hedule an inspection. UPPORTDATE11/29/2016 PHONE:575-746-5544</td>	eady for OCD inspection after P&A Protor's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ind lines have been removed from lease and well hedule an inspection. UPPORTDATE11/29/2016 PHONE:575-746-5544
OTHER: □ ☑ Location is r Image: State in the image: Sta	eady for OCD inspection after P&A A mator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/OUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c) All fluids have been removed from non- ind lines have been removed from lease and well hedule an inspection. DPPORTDATE11/29/2016