## EOG RESOURCES, INC. OPHELIA 27 FED COM #704H

# Hydrogen Sulfide Plan Summary

- A. All personnel shall receive proper H2S training in accordance with Onshore Order III.C.3.a.
- B. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
  - Well control equipment
    - a. Flare line 150' from wellhead to be ignited by flare gun.
    - b. Choke manifold with a remotely operated choke.
    - c. Mud/gas separator
  - Protective equipment for essential personnel.

Breathing apparatus:

- a. Rescue Packs (SCBA) 1 unit shall be placed at each breathing area, 2 shall be stored in the safety trailer.
- b. Work/Escape packs —4 packs shall be stored on the rig floor th sufficient air hose not to restrict work activity.
- c. Emergency Escape Packs —4 packs shall be stored in the doghouse for emergency evacuation.

#### Auxiliary Rescue Equipment:

- a. Stretcher
- b. Two OSHA full body harness
- c. 100 ft 5/8 inch OSHA approved rope
- d. 1-20# class ABC fire extinguisher
- H2S detection and monitoring equipment:

The stationary detector with three sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor / Bell nipple / End of flow line or where well bore fluid is being discharged.

(Gas sample tubes will be stored in the safety trailer)

- Visual warning systems.
  - a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
  - b. A colored condition flag will be on display, reflecting the current condition at the site at the time.
  - c. Two wind socks will be placed in strategic locations, visible from all angles.

### EOG RESOURCES, INC. OPHELIA 27 FED COM #704H

Mud program:

The mud program has been designed to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

Metallurgy:

All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.

Communication:

Communication will be via cell phones and land lines where available.

# EOG RESOURCES, INC. OPHELIA 27 FED COM #704H

**Emergency Assistance Telephone List** 

PUBLIC SAFETY:	8	911 or
Lea County Sheriff's Department		(575) 396-3611
Rod Coffman		
Fire Department:		
Carlsbad		(575) 885-3125
Artesia		(575) 746-5050
Hospitals:		()
Carlsbad		(575) 887-4121
Artesia		(575) 748-3333
Hobbs		(575) 392-1979
Dept. of Public Safety/Carlsbad		(575) 748-9718
Highway Department		(575) 885-3281
New Mexico Oil Conservation		(575) 476-3440
U.S. Dept. of Labor		(575) 887-1174
0.5. Dept. of Labor		(373) 667-1174
FOC Becomes Inc		
EOG (William)	Office	(422) 696 2600
EOG / Midland	Office	(432) 686-3600
C P III C I		
Company Drilling Consultants:	G 11	(100) 000 1010
Jett Dueitt	Cell	(432) 230-4840
Blake Burney		
Drilling Engineer		
Robert Brosig		(432) 686-3737
	Cell	(432) 770-0705
Drilling Manager		
Heath Work	Office	(432) 686-6716
	Cell	(903) 780-1179
Drilling Superintendent		
Jason Fitzgerald	Office	(432) 848-9029
	Cell	(318) 347-3916
H&P Drilling		
H&P Drilling	Office	(432) 563-5757
H&P 415 Drilling Rig	Rig	(432) 230-4840
		,
Tool Pusher:		
Johnathan Craig	Cell	(817) 760-6374
Brad Garrett		(02.)
Safety		
Brian Chandler (HSE Manager)	Office	(432) 686-3695
Ditali Challete (1151: Mallager)	Cell	` /
	Cell	(817) 239-0251

