			NMOC	D		
Form 3160-5 (June 2015) SOCD UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT DEC 27 2016 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entent MOCCD abandoned well. Use form 3160-3 (APD) for such proposals. Hobbs					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018	
					5. Lease Serial No. NMLC068281B	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. BUCK 17 FEDERAL 6H	
2. Name of Operator Contact: ASHLEY BERGEN CONOCOPHILLIPS COMPANY Contact: ASHLEY BERGEN E-Mail: ashley.bergen@conocophillips.com					 9. API Well No. 30-025-40901-0 	00-S1
3a. Address 3b. Phone No. (in Ph: 432-688-6				de) 10. Field and Pool or Exploratory Area JENNINGS		
MIDLAND, TX 79710						<u></u>
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 17 T26S R32E SWSE 28FSL 2064FEL					LEA COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
☑ Notice of Intent	X Notice of Intent		epen	□ Production (Start/Resume)		□ Water Shut-Off
□ Subsequent Report	□ Alter Casing		Iraulic Fracturing	□ Reclamation		U Well Integrity
	Casing Repair		v Construction	□ Recomplete		□ Other
☐ Final Abandonment Notice	Change Plans		g and Abandon g Back	☑ Temporarily Abandon □ Water Disposal		
testing has been completed. Final Al determined that the site is ready for f ConocoPhillips respectfully re 2018. The well is currently in a a rig on December 12-22, 201 done in accordance to IM-NM	inal inspection. quest to TA this wellbore approved shut in status th 6 to complete the TA of th -2016-017.	to preserve in at expires 1/	for a potential sid	detrack in like to bring		
 a fig on December 12-22, 2016 to complete the FA of this well phot to christmas. The work will be done in accordance to IM-NM-2016-017. The procedure for the TA of this well is as follows: Test Anchors as needed. Notify Champion we will be RU on well. Review JSA prior to RU on well. MI & RU WSU. Kill well, function test BOP. ND wellhead, NU BOP. POOH & LD tubing with gas lift mandrels/valves. Send tubing and gas lift mandrels/valves in for 						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #359403 verified by the BLM Well Information System						
For CONOCOPHILLIPS COMPANY, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANCHEZ on 12/13/2016 (17JAS0106SE)						
Name (Printed/Typed) ASHLEY BERGEN			Title REGUL	ATORY SPI	CIALIST	
Signature (Electronic Submission)			Date 11/30/2016		001	s X II.
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By	Title		EAU OF LA AVE	GE		
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	Office	A	CARLSBADHILLO			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any po to any matter w	erson knowingly and ithin its jurisdiction	willfully to ma	ke to any department or	agency of the United
(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** FOR RECORD ONLY MW/OCD 12/27/2016						

Additional data for EC transaction #359403 that would not fit on the form

32. Additional remarks, continued

inspection. Contact Engineering with inspection results (Melinda Alleman @ 337-412-4072). 7.RIH with bit, scraper, and tubing down to +/- 8,400?. 8.COOH with tubing, scraper, and bit. 9.TIH with CIBP (7?, 29lb/ft, P-110) and tubing. Set CIBP @ +/- 8,380? (KOP @ 8,378?). Shear off CIBP. POOH with tubing.

10.Dump 30 sacks cement on top of the CIBP.

11.RU pump truck to casing. Load casing with produced water. Test casing to 600 psi for 30 minutes. 12.Circulate packer fluid. Estimated total volume of casing with CIBP set will be an estimated 311 bbls.


13.Top off casing with packer fluid. 14.ND BOP. Secure wellhead. RD WSU. 15.Notify BLM Field Office 48 hours prior to MIT.


16.Chart well @ 550# for 30 minutes.

17. The MIT chart will be submitted to Regulatory for BLM submittal.

The current and proposed wellbore diagrams are attached.

A subsequent report with test results will be submitted as required following the TA completion.





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 12/15/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying guantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Buck 17 Federal 6H

- 1. Well is approved to be TA/SI for a period of 12 months or until 12/15/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 12/15/2017
- 4. COA's met at this time.