Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM-Hobbs **NMOCD** 

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

IAIA	IIAIAII	0002	1	

	SUNDRY NOTICES AND REPORTS ON WELLS	
	Do not use this form for proposals to drill or to re-enter an	
•	abandoned well. Use form 3160-3 (APD) for such proposals.	

abandoned we	II. Use form 3160-3 (API	D) for such p	oroposals.	CD	6. If Indian, Anottee	or Tribe Name			
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. 8910063990								
1. Type of Well		8. Well Name and No. DRICKEY QUEEN SAND UNIT 14							
☑ Oil Well ☐ Gas Well ☐ Oth						N SAND ONT 14			
<ol> <li>Name of Operator LEGACY RESERVES OPERA</li> </ol>	Contact: ATING E-Mail: jsaenz@le	IZ		9. API Well No. 30-005-00897-00-S1					
3a. Address PO BOX 10848 MIDLAND, TX 79702-7848	3b. Phone No. (include area code) Ph: 432-689-5200			10. Field and Pool or Exploratory Area CAPROCK-QUEEN					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,	)			11. County or Parish,	State			
Sec 33 T13S R31E SWSE Tra	act 13 660FSL 1980FEL	1		CHAVES COUNTY, NM					
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE C	OF NOTICE,	REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION					
Notice of Intent	☐ Acidize	☐ Dee	epen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off			
Notice of Intent ■	☐ Alter Casing	□ Нус	draulic Fracturing	☐ Reclam	ation	■ Well Integrity			
Subsequent Report	☐ Casing Repair	□ Nev	☐ New Construction		olete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	□ Plu	☐ Plug and Abandon		arily Abandon				
	☐ Convert to Injection	Plu	☐ Plug Back		Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Legacy is requesting the DQSU #14 be given an extension to the current TA status for one year. At this time Legacy is marketing the sale of the property to other operators, with hope that they will pick up the CO2 development work that is planned to include this well. We are requesting the one year extension to allow another operator time to decide the correct path for their development and use of this wellbore.  PROCEDURE: Notify OCD and perform MIT test.									
Well Has Been OSI Since MAR 01 1999 And TA Since AUG 21 2012. Well Will Be Approved For TA For One Additional Year After Successful MIT Test Is Done. This Will Be The Last One-Year TA Extension That Will Be Granted!  APPROVED FOR 3 MONTH PERIOD MAY 0 2 7017									
	#Electronic Submission: For LEGACY RE mmitted to AFMSS for pro	360738 verifie SERVES OPE cessing by DA		ell Information the Roswell 2/20/2016 (17					
Name (Printed/Typed) JOHN SA	THE OPERA	ATIONS EN	DINCER						
			1						

(Electronic Submission) 12/13/2016 Signature

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or

PETROLEUM ENGINEER Title


FEB 0 2 7017

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



SEE ATTACHED FOR CONDITIONS OF APPROVAL

## BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)