Form 3160-5 (June 2015)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
BY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

NMLC070337

5. Lease Serial No.

abandoned we	6. If Indian, Allottee o	r Tribe Name					
SUBMIT IN TRIPLICATE - Other instructions of Dage 2					7. If Unit or CA/Agreement, Name and/or No. 8910063990		
1. Type of Well ☐ Gas Well ☐ Other					Well Name and No. DRICKEY QUEEN SAND UNIT 35		
Name of Operator LEGACY RESERVES OPERATING E-Mail: jsaenz@legacylp.com					9. API Well No. 30-005-01035-00-S1		
3a. Address PO BOX 10848 MIDLAND, TX 79702-7848	(include area code) 9-5200		10. Field and Pool or Exploratory Area CAPROCK-QUEEN				
4. Location of Well (Footage, Sec.,			11. County or Parish, State				
Sec 10 T14S R31E NESW To 33.115589 N Lat, 103.811700			CHAVES COUNTY, NM				
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	ΓE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent	☐ Acidize	□ Dee	en	☐ Product	ion (Start/Resume)	☐ Water Shut-Of	ff
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete .	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Plu		and Abandon	▼ Temporarily Abandon			
	☐ Convert to Injection ☐ Plus		Back	☐ Water Disposal			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Procedure: Notify OCD and perform MIT test. Wellbore diagram attached. Legacy is requesting the DQSU #35 be given an extension to the current TA status for one year. At this time Legacy is marketing the sale of the property to other operators, with the hope that they will pick up the CO2 development work that is planned to include this well. We are requesting the one year extension to allow another operator time to decide the correct path for their development and use if this wellbore. APPROVED FOR 3 MONTH PERIOD ENDING MAY 0 1 2017							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #365273 verified by the BLM Well Information System For LEGACY RESERVES OPERATING, sent to the Roswell Committed to AFMSS for processing by DAVID GLASS on 02/01/2017 (17DRG0090SE)							
Name (Printed/Typed) JOHN SA	Title OPERA	TIONS ENG	SINEER				
Signature (Electronic	Submission)		Date 01/30/20	017			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By			Title PETA	Órann (i)	Carolina	FEB 0 1	2017
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ike to any department or	agency of the United	

(Instructions on page 2) ** BLM REVISED **

Legacy Reseves LP

FIELD:

Caprock

LEASE/UNIT:

Drickey Queen Sand Unit

COUNTY:

WELL: STATE: 35

New Mexico

Location: 1980' FSL & 1980' FWL, Sec 10K, T14S, R31E

SPUD: 11/53 COMP: 11/53

KB = 4,272'GL =

CURRENT STATUS: Producer Original Well Name: Phil - Mkx #2

API = 30-005-01035

-- No Surface Casing was set -- The Sundry Notice dated 11-04-53 states that "No surface water has been encountered in offset wells, and permission was previously obtained to pull the surface pipe and cement around the top of the 5 1/2". Similar procedure will be followed on this well."

2-7/8" 6.5# J-55 production tubing and PKR @ 100'.

Calc'd TOC @ 2392' w/enlargement=15%, yld=1.26 ft3/sk, 8-1/2" hole

CIBP @ 2800'

7" 20# @ 2875' w/100 sx

Top of Queen @ 2884':

Queen Open Hole: 2884' - 2893' (11-53)

PBTD - 2893' TD - 2893'

Well History:

Drickey Queen Sand Unit #35

(11-53) - Initial Completion:

Orig comp in open hole section 2884' - 2893'. IP 93 BOPD. Drld to 1240' w/ rotary tools and ran 8-5/8" prot. Csg. Set w/ mud and oil. Drld to 2875' w/ cable tools. Recovered 8-5/8" csg. Ran 7" csg @ 2875' and drld out to 2893' w/ cable tools

(03-08) - Workover: POH w/ rods, pump, and 2 7/8" production tubing. CO well to TD @ 2893'. Treated Queen interval (2884' - 2893') w/ 1500 gal zylene @ 3 BPM and 240 psi STP. Swabbed load back. Ran 2 7/8" 6.5# J-55 production tubing @ 2860'. Returned well to production (rod pump).

(06-08) - Workover: POH w/ rods, pump, and 2 7/8" production tubing. Repaired holes in 7" csg near the surface. Ultimately, dug out and replaced top 12' of 7". Ran 2-7/8", 6.5#, J-55 tubing with TAC @ 2804', EOT @ 2812'. Installed PCP and rods.

(02-16) - Workover:

POH w/ rods, pump, and 2 7/8" production tubing. Run CIBP and set @ 2800'. Run and set PKR @ 100'. TA well

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)