

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-39635
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. AO-3071
7. Lease Name or Unit Agreement Name Hansen State
8. Well Number 14
9. OGRID Number 873
10. Pool name or Wildcat Tubb

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/>	
2. Name of Operator Apache Corp.	
3. Address of Operator P O box Drawer D Monument NM 88265	
4. Well Location Unit Letter <u>B</u> : <u>910</u> feet from the <u>N</u> line and <u>2310</u> feet from the <u>E</u> line Section <u>16</u> Township <u>20S</u> Range <u>37E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3541 GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING CONVERSATION <u>RBDMS MB</u> RETURN TO <u>TA PM</u> CSCG <u>ENVIRO</u> CHG LOC INT TO PA <u>P&A NR</u> P&A R OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <u>TA TEST</u> <input checked="" type="checkbox"/>
---	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 5211-5246

Perfs 5612-5724

1. MIRU. POOH & LD RODS. NU-BOP. POOH W/ TBG
2. SET CIBP @ 5562' & DUMP BAIL 35' CMT ON BP. SET CIBP @ 5170' & DUMP BAIL 35' CMT ON BP.
3. RIH W/ TBG & LOAD CSG W/ PKR FLUID & TEST TO 550# FOR 30 MINUTES.
4. POOH & LD TBG. NOTIFY OCD 24 HRS IN ADVANCE OF TA TESTING.
5. MEET OCD REP. GEORGE BOWER.
6. LOAD CSG 1/2 BBL PKR FLUID. PRESSURE UP TO 580#.
7. RECORD TEST ON CHART RECORDER FOR 32 MINUTES.
8. ENDING PRESSURE 570#.
9. REQUEST TA STATUS FOR WELL.

This Approval of Temporary
Abandonment Expires 3/10/2021

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Sisk TITLE SR. PUMPER DATE 3/10/2017

Type or print name Joel Sisk E-mail address: joel.sisk@apacheccorp.com PHONE: 575-441-0793

For State Use Only

APPROVED BY: Maureen Brown TITLE AO/II DATE 3/14/2017

Conditions of Approval (if any):

PRINTED IN U.S.A.

5 6 PM

7

8

9

10

11

MIDNIGHT

1

2

3

4

5

6

AM

7

8

9

10

11

NOON

Graphic Controls

DATE 3/10/17
BR 2221

START

T/A STATUS TEST

Apache

House #14
30-025-39635

B-14-205-374
CALLS DATE - 9/2/16
SER # 594019

Start 580k
End 570k
32 min

Super Power-coo
mpe/hskey

END