Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources		iral Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-025-28337
811 S. First St., Artesia, NM 88210		DIVISION	5. Indicate Type of Lease
District I – (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240  District II – (575) 748-1283  811 S. First St., Artesia, NM 88210  District III – (505) 334-6178  1000 Rio Brazos Rd., Aztec, NM 87410  District IV – (505) 476-3460  Energy, Minerals and Natural Resources  Energy, Minerals and Natural Resources  Solution Servation DIVISION  South St. Francis Dr.  Santa Fe, NM 87505		ncis Dr.	STATE FEE 🔼
		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NGC			
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO PRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		South Hobbs (G/SA) Unit	
1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned		8. Well Number 133	
Name of Operator     Occidental Permian, Ltd		9. OGRID Number 157984	
3. Address of Operator		10. Pool name or Wildcat	
HCR 1 Box 90 Denver City, TX 79323		Hobbs (G/SA)	
4. Well Location			
Unit Letter E: 1840 feet from the North line and 748 feet from the West line,			
Section 3 Township 19-S Range 38-E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3612.8' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORL			
TEMPORARILY ABANDON			
DOWNHOLE COMMINGLE	IOLTIFLE COMPL	CASING/CEWENT	JOB 🗆
CLOSED-LOOP SYSTEM			
OTHER: TA status extension requ	uest 🔼	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Pun MI tost to gain extension on temporary abandoned status			
Run MI test to gain extension on temporary abandoned status.			
O The			
Condition of Approval: notify			
OCD Hobbs office 24 hours			
and the state of t			
prior of running MIT Test & Chart			
		- manager	* 8.52
			3.24
Spud Date:	Rig Release Da	ita:	
Spud Date.	Kig Kelease Da	itc.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE DATE 03/29/2017			
Type or print name Mendy . Johnson E-mail address: mendy_johnson@oxy.com PHONE: 806-592-6280			
For State Use Only			
APPROVED BY: DATE 4/3/2017			
Conditions of Approval (if any):			

NO PROD REPORTED - 22 MOUTHS