
Submit 1 Copy To Appropriate District	Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Minerals and Natural Resources		Form C-103	
District I – (575) 393-6161			Revised August 1, 2011 WELL API NO.	
			30-025-31814	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178		cis Dr	5. Indicate Type of I	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM RECEIVED 1220 South St. Francis Dr. Santa Fe, NM 87505		-05	6. State Oil & Gas L	FEE
			0. State Off & Gas L	Lease NO.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or U	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		VACUUM GLORIETA WEST UNIŤ		
1. Type of Well: Oil Well Gas Well Other INJECTOR			8. Well Number: 31	
2. Name of Operator Chevron U.S.A. INC.			9. OGRID Number 4323	
3. Address of Operator			10. Pool name or Wildcat	
6301 DEAUVILLE BLVD, MIDLAND, TX 79706 RM.N3002			VACUUM GLORIETA	
4. Well Location Unit LetterI : 2520 feet from theSOUTH line and feet from the LAST line				
Section 25		Range 34E	NMPM	County Lea
	ion (Show whether DR, 1	U		County Lea
3982' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT				T TO PA <u> 🏧 </u> A NR
		CASING/CEMENT		A R
	_			
OTHER: 13. Describe proposed or completed operati			in a pertinent dates	including estimated date
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC.				
 13. Describe proposed or completed operations. (Clearly state all performance) of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. before operations begin. 				
2. MIRU. NDWH. NU BOPE.				
3. Tag CIBP and cement@5,940' and spot 25sx of cmt. on top. Circulate well w/9.5 ppg mud.				
Pressure test casing.				
4. Spot 25sx of Class "C" cement from 5,058'-4,858', WOC&Tag. (DV Tool)				
5. Spot 25sx of Class "C" cement from 2,876'-2,676', WOC&Tag. (B.Salt)				
6. Spot 35sx of Class "C" cement from 1,600'-1,300', WOC&Tag. (T.Salt/Shoe)				
7. Spot 40sx of Class "C" cement from 350' to surface. (FW/surface)				
8. Verify cement to surface on all casings. Cut off wellhead and anchors 3' below grade. Weld on				
dryhole marker and clean location.				
Closed loop above ground tank system will be used for fluids.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE M. July and	TITLE Proje	ect Manager	DATE	04/05/17
Type or print name <u>M. Lee Roark</u> For State Use Only	E-mail address:	LRoark@Chevron	.com PHONE:	(432)-687-7279
heathill	DI	E C	reciplist	4-10-2017
APPROVED BY: Machele Mathematica Conditions of Approval (if any):	TITLE TERO	wm rengr. J	DATE	4-10-2017



WELLBORE DIAGRAM VACUUM GLORIETA WEST UNIT #31 PROPOSED

AM LAND

