

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-62563 ✓
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>INJECTION</u> HOBBS OGD		5. Indicate Type of Lease STATE FEE X ✓
2. Name of Operator State of New Mexico formerly Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 811 South 1 st Street, Artesia, NM 88210		7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit ✓
4. Well Location Unit Letter <u>C</u> : <u>330</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line Section <u>5</u> Township <u>9S</u> Range <u>29E</u> NMPM Chaves County ✓		8. Well Number <u>63</u> ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number
		10. Pool name or Wildcat Twin Lakes; San Andres (Assoc) ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐ P

TEMPORARILY ABANDON ☐ C

PULL OR ALTER CASING ☐ M

DOWNHOLE COMMINGLE ☐

INT TO PA

P&A NR PMS

P&A R

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING/CEMENT JOB ☐

ALTERING CASING ☐

P AND A XX

OTHER: _____

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Mark Whitman TITLE P.E.S. DATE 05/08/2017

Conditions of Approval (if any):

Plugging Report TLSAU #63

4/28/2017 Moved rig and equipment to location.

5/1/2017 Moved remaining equipment to location. Worked on road to location and rigged up. Removed wellhead flange and there was no pipe in the well. Well bore was full of fluid. SION

5/2/2017 Installed BOP. RIH with workstring and tag existing CIBP at 2744'. Casing tested good to 650#. Circulated MLF and spotted 25 sx cement at 2744'. POOH to 2275' and spotted 25 sx cement. POOH to 1007' and spotted 25 sx cement. POOH to 270' and circulated cement to surface with 30 sx cement. SION.

5/3/2017 Cut off wellhead and filled up both strings with 15 sx cement. Installed marker, cut off anchors, and cleaned pit.