

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAY 22 2017

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-60802
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE FEE X /
2. Name of Operator State of New Mexico formerly Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 811 South 1 st Street, Artesia, NM 88210		7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit /
4. Well Location Unit Letter I : 1650 feet from the South line and 990 feet from the East line Section 31 Township 8S Range 29E NMPM Chaves County /		8. Well Number 042 /
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864 /
		10. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Work done attempting to P&A X

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

Rig Down Move off on 05/19/2017 due to funding.
Will rig up & complete job at a later date.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only **FOR RECORD ONLY**

APPROVED BY: _____ TITLE _____ DATE 05/22/2017

Conditions of Approval (if any):

Report of Work TLSAU #42

5/11/2017 Worked on roads and location (5/10/2017). Moved in and rigged up. Dug out cellar. No pipe in the well. Installed BOP. Rigged up wireline and made gauge ring run. Could not get past 104'. Moved in work string and RIH with bit and scrapper. Had to work pipe to make hole starting at 1425'. Stacked out at 2043'. Attempted to wash down but could not get any further. POOH and last joint was bent badly. RIH with perforated sub and bull plug. Stacked out at 1443'. Called OCD. Spotted 30 sx Class C with CaCl and POOH. No circulation. POOH and SION.

5/12/2017 RIH and tagged @ 1434'. No fill from cement. Spotted 25 sx cement w/CaCl. WOC and tagged at 1434' again. Pumped 50 sx w/ CaCl. SION.

5/15/2017 RIH and tagged @ 1439. Pumped 10 bbls LCM followed by 30 sx Class C with CaCl. WOC and tagged at 1404'. RIH with packer and set at 950'. Pumped down tubing below the packer. Got communication with 10 bbls out of the 4 1/2" casing and the 8 5/8" casing. Same results at 1266', 633', & 316'. POOH with packer and closed BOP. Could pump down 4 1/2" casing at 6 bbl/min @ 50 #. Called OCD. RIH to 1266' and spotted 30 sx cement with CaCl. POOH and SION.

5/16/2017 RIH and tagged at 1404' again. Was pulling out of the hole to spot cement at 1014' when a collar hung on a partially opened BOP and tore the wellhead off. Repaired the wellhead and spotted 30 sx Class C cement with paper and CaCl at 1014'. POOH and SION. Took off supervisor time, circulating tank, and 6 hrs of rig time to make up for our mistake and wasting half a day.

5/17/2017 RIH and tagged at 1404'. Removed BOP and dumped 27 cubic feet of 1/2" screened chat down the 4 1/2" casing. RIH with tubing and tagged at 1341'. Spotted 30 sx Class C on top of fill and POOH. SION

5/18/2017 RIH and tagged at 1339'. Spotted 30 sx cement with CaCl at 1339'. WOC and tagged at 1339'. Dumped another 27 cubic feet of 1/2" chat down the 4 1/2" casing. Tagged at 1176'. Spotted 30 sx cement with CaCl at 1140'. POOH and SION

5/19/2017 Tagged at 1176'. RIH with packer and set at 792'. Pumped down tubing under the packer. Could pump 5 bbl/min at 150 #. POOH with packer. Dumped 27 cubic feet of chat down 4 1/2" casing. Tagged again at 1176'. Dumped 27 cubic feet of chat down 4 1/2" casing. Tagged at 1165'. Dumped 27 cubic feet of chat down 4 1/2" casing. Tagged at 894'. Laid down remaining tubing and SION. Rigged down