1								
B SUNDRY Do not use th					BS (2 5 201	OMB N		137 2018
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2		EIVE	7. If Unit or CA/Agree	ement, Na	me and/or No.
1. Type of Well ⊠ Oil Well □ Gas Well □ Ot	her				SIVE	8. Well Name and No. PIPELINE DEEP	5 FEDER	AL 03
2. Name of Operator CIMAREX ENERGY COMPA	Contact:	AMITHY CRA @cimarex.com	AWFORD			9. API Well No. 30-025-37196-0	00-C2	
3a. Address 202 S CHEYENNE AVE. SUI TULSA, OK 74103	TE 1000	3b. Phone No Ph: 432.62		i code)		10. Field and Pool or MultipleSee A		y Area
4. Location of Well (Footage, Sec., 1	T., R., M., or Survey Description	1)				11. County or Parish,	State	
Sec 5 T19S R34E SWNE 165 32.692416 N Lat, 103.578315	50FNL 1340FEL 🗸 5 W Lon					LEA COUNTY,	NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATUI	RE OF	NOTICE,	REPORT, OR OTI	HER DA	TA
TYPE OF SUBMISSION			TY	PE OF A	ACTION			
Notice of Intent	Acidize	Dee Dee	pen		Product	ion (Start/Resume)	🗖 Wa	ter Shut-Off
_	□ Alter Casing	🗖 Hyd	Iraulic Fractu	uring	Reclam	ation	U We	ll Integrity
Subsequent Report	Casing Repair	New	v Constructio	on	Recomp	olete	Oth Oth	ler
Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abando g Back		 Temporarily Abandon Water Disposal 			
following completion of the involve testing has been completed. Final A determined that the site is ready for Notify BLM 24 hours prior to s Max Treating Pressure = 6,00 7700' of 3-1/2" 12.95# P110 v 1. Hold operational safety me 2. MIRU Pulling unit. 3. Kill well if necessary w/ 2% 4. TOOH w/ Rods, Pump, and 5. PU 4-3/4" bit and 5-1/2" ca 6. TOOH, LD bit and scraper. 7. TIH to 1 1,350' and set CIB 8. Release from the CIBP and	 Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandomment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Notify BLM 24 hours prior to starting operations Max Treating Pressure = 6,000 psi 7700' of 3-1/2" 12.95# P110 will need to be rented for frac string 1. Hold operational safety meeting on location; discuss all risk and potential dangers. 2. MIRU Pulling unit. 3. Kill well if necessary w/ 2% KCL. 4. TOOH w/ Rods, Pump, and Tbg. 5. PU 4-3/4" bit and scraper. PU 5-1/2" CIBP. 7. TiH to 14,350' and set CIBP. — 11,3000 8. Release from the CIBP and PU 1 joint. Circulate well w/ 315 bbls of 2% KCL. 							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #369590 verified by the BLM Well Information System For CIMAREX ENERGY COMPANY OF CO, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 03/15/2017 (17PP0362SE) Name(Printed/Typed) AMITHY CRAWFORD Title REGULATORY ANALYST								
Signature (Electronic Submission) Date 03/13/2017								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
the Wells			Title	the				Date 5/19/17
Conditions of approval, if any, are attached certify that the applicant holds legal or equilibrium of the appl	Approved By A WWW Date Title Date 7/7/// Date 7/7/// Date 7/7///							
States any false, fictitious or fraudulent	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2) ** BLM REV	(Instructions on page 2) ** BLM REVISED **							
mos/aca 5/25/2017								

Additional data for EC transaction #369590 that would not fit on the form

10. Field and Pool, continued

QUAIL RIDGE

1

32. Additional remarks, continued

9. RIH to 11,354' and spot balanced plug w/ 55 sxs of class H cement on top of CIBP also covering

the top of the Wolfcamp formation. 10. PU tbg to 10,600'. Reverse circulate 22 bbls of mud-laden fluids. Flush with 147 bbls of 2%

KCL, leaving mud fluids at EOT in the wellbore.

Allow proper time for cement to set up.
 TIH and tag cement plug @ 10,639'.
 TOOH. PU another 5-1/2" CIBP.
 TIH to 9,680 and set CIBP.
 Release from the CIBP.

CIBP to be set 100'-SO' above parts.

16. PU 1' off the CIBP and spot balanced plug w/ 50 sxs of class H cement on top of CIBP also covering the top of the Bone Spring formation.

17. PU tog to 9,000'. Reverse circulate 80 bbls of 2% KCL to ensure tubing is clean.
18. TOOH w/ 2-7/8" tbg and LD.
19. RU WL. RIH w/ Select fire perforating guns and a gamma ray gun.

a. Correlate gamma ray back to Halliburton "Dual Laterolog Microguard" dated 25-DEC-2005
20. Perforate 7800' - 7812' & 5720' - 5742' w/ 3 SPF, 041" EH, and 120-degree phasing.
21. RD WL. TIH w/ 7,700' of 3-1/2" 12.95# P110 Tbg, 3-1/2" x 2-7/8" XO, and 2-7/8" x 5-1/2"

Treating packer to 7,700'. a. Hydrotest 3-1/2" tbg to 6,000 psi while TIH. 22. Set Packer in 20 pts Compression at 7,700'.

23. RU Frac Crew and pressure test lines to MTP: 6,000 psi.

24. Frac the 1st stage w/ 32,000 lbs of proppant and 30,000 gals of slickwater with 17# Linear Gel and 17# XL Borate.

25. PU 3-1/2" tbg and treating packer to 5,600'. Set packer in 20 pts compression.

26. Frac the 2nd stage w/ 42,000 lbs of proppant and 35,481 gals of slickwater with 17# Linear Gel and 17 # XL Borate.

27. RU flowback equipment in such a way that production can be turned to the battery once hydrocarbons are detected.

28. Flow back well until it dies (if it flows at all).

29. TOOH w/ 3-1/2" tbg and packer. 30. RIH w/ 2-7/8" tbg and rods.

31. Return to production.

DISTRICT J 1825 N. French Dr., Hobts, NM 88240 DISTRICT II 811 South First, Arlesis, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-102 Revised March 17, 1999

Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

OIL CONSERVATION DIVISION 2040 South Pacheco

Santa Fe, New Mexico 87504-2088

D AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number	F	oo) Code			Pool Name		
30-025-37196 96531 Dios Mano; Delawar					, South		
Property Code	Property Name Well N PIPELINE DEEP "5" FEDERAL 3						ımber
OGRID No. 162683 Operator Nome Cimarex Energy Co. of Colorado						Elevation 3869'	
		Surfa	ce Loca	ation			
UL or lot No. Section 7	Township Range	Lot Idn Feet fre	om the	North/South line	Feel from the	East/West line	County
G 5	19 S 34 E	1650 NORTH		1340 EAST		LEA	
	Bottom	Hole Location 1	lf Diffe	rent From Sur	face		
UL or lot No. Section 7	Township Range	Lot Idn Feet fro	om the	North/South line	Feel from the	East/West line	County
Dedicated Acres Joint or 1 40	Infill Consolidation (613 D	HC-3883			
NO ALLOWABLE WII	LL BE ASSIGNED TO OR A NON-STAN	TO THIS COMPLE	TION U	NTIL ALL INTER		EN CONSOLIDA	ATED
		3865. Pipeline Deep 5 Fed 3862. Lot.: N32*41'32.7 Long.: W103*34'4	#3 (3874.9' 	I hereby contained hereis best of my know Signature <u>AM</u> Printed Nam <u>Regu</u> Title <u>UDATE</u> SURVEYOU I hereby certifi on this plat to actual surveys supervison or correct to the <u>Date</u> Date Survey Signature & Profersioner	Alatory Analy 03/13/2017 OR CERTIFICAT that the well local as plotted from freto made by me or that the same is a best of my belie ther 1 2004 Or 1 2004 Sent of the same is a best of a belie the from freto a best of a belie the from freto the freto freto freto freto the freto freto freto freto the freto freto freto freto the freto freto freto the freto freto freto freto the freto freto freto the freto fre	formation ete to the d d /st filon d notes of under my true and f.



AFE No:

Procedure Sheet – Hobbs District

PLEASE COMMENCE WITH WORK PER PROCEDURE

Pipeline Deep 5 Federal 3

Recomplete Well in Cherry Canyon and Lower Brushy

Current Well Data:

КВ	28' above GL
TVD/PBTD	13,742'/13,626'
KOP	N/A Vertical Well
Perfs	Bone Spring (9692' – 9735')
	Wolfcamp (11,361' - 11,378')

Casing

Size	Weight	Grade	Thread	Set at	Cmt	Remarks
13-3/8"	48#	H-40	ST&C	432'	410 sx	cir cmt
9-5/8"	40#	K-55	LT&C	3518'	1200 sx	cir cmt
5-1/2"	17#	P-110	BT&C	13742'	2155 sx	TOC @ 1250'

Tubing

Tubing			
Quantity	Description	Length	Setting Depth
289	2-7/8" 6.5# L-80 8rd EUE Tubing	9,022.58	9050.58
1	TAC 5.5 X 2 7/8" w Carbide Slips	2.7	9053.28
74	2-7/8" 6.5# L-80 8rd EUE Tubing	2,366.68	11419.96
1	Mechanical SN	0.8	11420.76
1	Bull plugged perforated sub	4.1	11424.86
Rods			
Quantity	Description	Length	Setting Depth
1	1.5" x 24' SM Polished rod	24	24
1	Pony Rods 2-2' N-97	4	28
121	1" Grade 97 Rods	3,025.00	3053
122	7/8" Grade 97 Rods	3,050.00	6103
205	3/4" Grade 97 Rods	5,125.00	11228
1	1.5" X 25	150	11378
1	25-125-24 RHBM w striner nipple	24	11402

Procedure:

Notify BLM 24 hours prior to starting operations Max Treating Pressure = 6,000 psi 7700' of 3-1/2" 12.95# P110 will need to be rented for frac string

> Page **1** of **3** Please call Kody Murphy at 432.620.1951 if you have any questions



- 1. Hold operational safety meeting on location; discuss all risk and potential dangers.
- 2. MIRU Pulling unit.
- 3. Kill well if necessary w/ 2% KCL.
- 4. TOOH w/ Rods, Pump, and Tbg.
- 5. PU 4-3/4" bit and 5-1/2" casing scraper. RIH to 11,355'.
- 6. TOOH, LD bit and scraper. PU 5-1/2" CIBP.
- 7. TIH to 11,350' and set CIBP.
- 8. Release from the CIBP and PU 1 joint. Circulate well w/ 315 bbls of 2% KCL.
- 9. RIH to 11,354' and spot balanced plug w/ 55 sxs of class H cement on top of CIBP also covering the top of the Wolfcamp formation.
- PU tbg to ±10,600'. Reverse circulate 22 bbls of mud-laden fluids. Flush with 147 bbls of 2% KCL, leaving mud fluids at EOT in the wellbore.
- 11. Allow proper time for cement to set up.
- 12. TIH and tag cement plug @ \pm 10,639'.
- 13. TOOH. PU another 5-1/2" CIBP.
- 14. TIH to 9,680' and set CIBP.
- 15. Release from the CIBP.
- 16. PU 1' off the CIBP and spot balanced plug w/ 50 sxs of class H cement on top of CIBP also covering the top of the Bone Spring formation.
- 17. PU tbg to ± 9,000'. Reverse circulate 80 bbls of 2% KCL to ensure tubing is clean.
- 18. TOOH w/ 2-7/8" tbg and LD.
- 19. RU WL. RIH w/ Select fire perforating guns and a gamma ray gun.
 - a. Correlate gamma ray back to <u>Halliburton "Dual Laterolog Microguard" dated 25-DEC-</u> 2005
- 20. Perforate 7800' 7812' & 5720' 5742' w/ 3 SPF, 041" EH, and 120-degree phasing.
- RD WL. TIH w/ 7,700' of 3-1/2" 12.95# P110 Tbg, 3-1/2" x 2-7/8" XO, and 2-7/8" x 5-1/2" Treating packer to 7,700'.
 - a. Hydrotest 3-1/2" tbg to 6,000 psi while TIH.
- 22. Set Packer in 20 pts Compression at 7,700'.
- 23. RU Frac Crew and pressure test lines to MTP: 6,000 psi.
- 24. Frac the 1st stage w/ 32,000 lbs of proppant and 30,000 gals of slickwater with 17# Linear Gel and 17# XL Borate.


Page 2 of 3 Please call Kody Murphy at 432.620.1951 if you have any questions



- 25. PU 3-1/2" tbg and treating packer to 5,600'. Set packer in 20 pts compression.
- 26. Frac the 2nd stage w/ 42,000 lbs of proppant and 35,481 gals of slickwater with 17# Linear Gel and 17 # XL Borate.
- 27. RU flowback equipment in such a way that production can be turned to the battery once hydrocarbons are detected.
- 28. Flow back well until it dies (if it flows at all).
- 29. TOOH w/ 3-1/2" tbg and packer.
- 30. RIH w/ 2-7/8" tbg and rods.
- 31. Return to production.

	Curre	ent
CIMAREX		Cimarex Energy Co. of Colorado PIPELINE DEEP "5" FED #3 API 30-025-37196 1650' FNL & 1340' FEL, Sec 5, Unit G, T19S R34E Lea County, NM GL:3869' KB: 3897'
13 3/8'' 48# H-40 csg @ 432' Cmt w/410 sx, circ to surface		17 1/2" hole to 435' 5-1/2" TOC = 1200' by TS
9 5/8" 40# K55 csg @ 3518' Cmt w/1200 sx, circ to surface		12 1/4" hole to 3500'
DV Tool @ 9828' Cmt w/995 sx Interfill "C" Tail w/420 sx Super "H" TOC @ 1250' by CBL		
		Bone Spring: 9692' to 9735', 3 JSPF, 42 holes (3/26/07) Wolfcamp: 11,361' to 11,378' w/ 3 JSPF (3/13/07)
		CIBP @ 13,135' + 35' cmt (3/13/2007) U Morrow: 13,158' - 13,400', 6 JSPF (3/29/06) U Morrow: 13,481' to 13,495', 6 JSPF (3/12/06)
5 1/2" 17# P-110 csg @ 13,742' Cmt w200 sx Interfil "H" Tail w/500 sx Super "H" DV Tool @ 9828'	PBTD: 13626' TD: 13,742'	L Morrow: 13,441' to 13,550', 3 JSPF, 60 holes, (1/24/06)
		M Ketter, J Piwet

.



M Ketter, J Piwetz

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

,

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken: From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted