## EOG RESOURCES, INC. NEPTUNE 10 STATE COM #705H

# Hydrogen Sulfide Plan Summary

- A. All personnel shall receive proper H2S training in accordance with Onshore Order III.C.3.a.
- B. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
  - Well control equipment
    - a. Flare line 150' from wellhead to be ignited by flare gun.
    - b. Choke manifold with a remotely operated choke.
    - c. Mud/gas separator
  - Protective equipment for essential personnel.

Breathing apparatus:

- a. Rescue Packs (SCBA) 1 unit shall be placed at each breathing area, 2 shall be stored in the safety trailer.
- b. Work/Escape packs —4 packs shall be stored on the rig floor th sufficient air hose not to restrict work activity.
- c. Emergency Escape Packs —4 packs shall be stored in the doghouse for emergency evacuation.

Auxiliary Rescue Equipment:

- a. Stretcher
- b. Two OSHA full body harness
- c. 100 ft 5/8 inch OSHA approved rope
- d. 1-20# class ABC fire extinguisher

H2S detection and monitoring equipment:

The stationary detector with three sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor / Bell nipple / End of flow line or where well bore fluid is being discharged.

(Gas sample tubes will be stored in the safety trailer)

- Visual warning systems.
  - a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
  - b. A colored condition flag will be on display, reflecting the current condition at the site at the time.
  - c. Two wind socks will be placed in strategic locations, visible from all angles.

## EOG RESOURCES, INC. NEPTUNE 10 STATE COM #705H

#### Mud program:

The mud program has been designed to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

# Metallurgy:

All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.

#### Communication:

Communication will be via cell phones and land lines where available.

<b>Emergency Assistance Telephon</b> <b>PUBLIC SAFETY:</b>	e List		911 or
Lea County Sheriff's Department		(575)	396-3611
Rod Coffman		(575)	570-5011
Fire Department:			
Carlsbad		(575)	885-3125
Artesia		· · ·	746-5050
Hospitals:		(575)	10 0000
Carlsbad		(575)	887-4121
Artesia			748-3333
Hobbs		· /	392-1979
Dept. of Public Safety/Carlsbad		· /	748-9718
Highway Department			885-3281
New Mexico Oil Conservation		. /	476-3440
U.S. Dept. of Labor			887-1174
0.5. Dept. of Labor		(575)	00/-11/4
EOG Resources, Inc.			
EOG / Midland	Office	(432)	686-3600
		( )	
Company Drilling Consultants:			
David Dominque	Cell	(985)	518-5839
Mike Vann	Cell		980-5507
		()	
Drilling Engineer			
Steve Munsell	Office	(432)	686-3609
	Cell	. ,	894-1256
Drilling Manager		. /	
Heath Work	Office	(432)	686-6716
	Cell	· /	780-1179
Drilling Superintendent			
Jason Fitzgerald	Office	(432)	848-9029
	Cell	~ /	347-3916
H&P Drilling		. ,	
H&P Drilling	Office	(432)	563-5757
H&P 651 Drilling Rig	Rig		509-7131
	0		
Tool Pusher:			
Johnathan Craig	Cell	(817)	760-6374
Brad Garrett			
Safety			
Brian Chandler (HSE Manager)	Office	(432)	686-3695
	Cell	(817)	239-0251
		. /	

# EOG RESOURCES, INC. NEPTUNE 10 STATE COM #705H