Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.		
District II - (575) 748-1283	OIL CONSERVATION DIVISION				
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	11 5.1 115. 51., 741.6514, 141.4 602.10				, , , , , , , , , , , , , , , , , , ,
1000 Rio Brazos Rd., Aztec, NM 87410		Santa Fe, NM 87505		of Lease FEE	x /
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	541141 10, 11111 07			as Lease No.	Δ /
87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			7. Lease Name o	r Unit Agreemer	nt Name
			Twin Lakes San Andres Unit		
			8. Well Number		
2. Name of Operator					
State of New Mexico formerly Bl	9. OGRID Number 3 00825				
3. Address of Operator			10. Pool name or Wildcat		
811 South 1st Street, Artesia, NM 88210			Twin Lakes; San Andres (Assoc)		
4. Well Location					
Unit LetterP:990feet from theSouth line and990feet from theEast line \rightarrow					
Section 6 Township 9S Range 29E NMPM Chaves County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ REMEDIAL WOR					
TEMPORARILY ABANDON INT TO PA COMMENCE DR				P AND A	XX
PULL OR ALTER CASING P&A NR X CASING/CEMEN			JOB 🗆		
DOWNHOLE COMMINGLE P&A R					
OTHER:		OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
SEE ATTACHED					
I hereby certify that the information	n above is true and complete to the be	est of my knowledge	and belief.		
SIGNATURE	TITLE		DA	ATE	
Type or print name E-mail address:		:	PHONE:		
For State Use Only	0.			,	1
APPROVED BY:	Whitele P.E	5	DA	TE 06/15	12017
Conditions of Approval (if any):					

Plugging Report TLSAU # 89

6/5/2017 Move in equipment and rig up. Had to install 1 anchor. Could not get wellhead cap loose. Removed old wellhead and installed a different one. No pipe ion the well. Moved in workstring. Installed BOP and SION.

RIH with gauge ring and sat down at 650'. RIH with bit and scrapper and tagged hard at 1741'. Could not make hole by turning or pumping. POOH with scrapper and picked up packer. Set packer at 1519' and pumped down tubing under the packer. Communicated up the 4 ½" casing . Had same results at 1709' and 1013'. POOH with packer. RIH open ended to 1741' and spotted 35 sx cement with CaCl. WOC and tagged at 1741'. Spotted another 35 sx with CaCl at 1741' and SION.

RIH and tagged cement at 1654'. RIH with packer and tested casing above packer at 253'. Held 250#. Set packer at 696". Tested above packer. Communicated with 4 ½" casing. Set packer at 506' and tested above packer. Held 250#. Pumped below packer and got a good blow up the surface annulus. Started communicating up the 4 ½" casing after 15 bbls while trying to get fluid up the surface annulus. Developed a small hole in the 4 ½" casing somewhere above the packer. Consulted with OCD rep. on location. Pumped 50 sx cement with CaCl under packer and displaced to 600'. POOH with packer and WOC. Tagged cement at 221'. Closed BOP blinds and tested 4 ½" casing to 250#. Perforated 4 ½" casing at 174'. Established circulation and pumped cement down 4 ½" casing to perfs at 174' and up annulus to surface. Took 55 sx. Rigged down

6/8/2017 Cut off wellhead. Cement was to surface on both strings. Installed marker and cut off anchors. Cleaned pit and cleared location