Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

NMOCD Hobbs



FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

				-
i.	Lease	Serial	No.	
4	00670	30		

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. LUSK SEVEN RIVERS UNIT 1. Type of Well 8. Well Name and No Oil Well Gas Well Other LUSK SEVEN RIVERS UNIT 003 2 Name of Operator 9. API Well No. 30-025-20415 Remnant Oil Operating LLC 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area P.O. BOX 5375 MIDLAND, TX 79704 LUSK: 7 RIVERS NORTH 432-242-4965 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 11. Country or Parish, State LEA. NM 660 ENL 660 EWL: LLD SEC 19S R32E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen ✓ Production (Start/Resume) Water Shut-Off Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing Casing Repair New Construction Recomplete Other ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 3/8/16 MIRU, UNHANG WELL, UNSEATED PUMP. POOH WITH PUMP AND RODS. VISUALLY INSPECT RODS WHILE POOH, OK, NO WELLHEAD, WAIT ON ADAPTER FLANGE AND NU BOP, TUBING WAS NOT FREE. SET WEIGHT ON TUBING, PULL UP TO NEUTRAL POSITION AND TURNED TUBING TO TO RIGHT AND RELEASED PACKER. LD 15 JTS. SWI. SDON. FINISHED POOH WITH TUBING.PULLED SLOW DUE TO DRAG WHILE PULLING PACKER. PU 3-7/8" BIT, 4-1/2" CASING SCRAPPER AND PU 2-3/8" TUBING TO 3883' (PBTD). FELT CASING SCRAPPER WORK THROUGH PERFS. POOH WITH 10 JTS.SWISDON. 3/10/16 RIH WITH 10 JTS. CIRC WELL CLEAN WITH 60 BBLS FW. POOH WITH BIT AND SCRAPPER. RIH WITH 2-3/8" STANDARD SEE ATTACHED 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) CARIE STOKER Title REGULATORY AFFAIRS COORDINATOR Date 05/05/2016 Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

litle

Office

Approved by	ACCE	PTED	FORF	₹E	CORD
	(THERE	SGD:	DAVID	包:	O FATE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 100 Pand Title 43 U.S.C. Section 1212, make it a crime for any person knowl

fictitious or fraudulen categories of temps of the first of the first

(Instructions on page 2)

Accepted For Record Only! Approval Subject To Putting Well On Continuous Production And Keeping Well On Continuous Production Or Plugging Well With An Approved Plugging Program!

Date

LUSK SEVEN RIVERS UNIT #003

3/11/16

TUBING ON SLIGHT VACUUM, ND BOP. NU WELLHEAD. PREP FOR RODS. RIH WITH PUMP AND RODS. SPACED OUT WELL AND HWO. LOADED TUBING, PRESSURED PUMP TO 500 PSI. WELL PUMPED A FEW MINUTES AND QUIT. LONG STROKED AND REPRESSURED PUMP. NO PUMP ACTION. UNHANG WELL, SET RODS DOWN ON PUMP. PULLED UP HOLE 1 JT AND LANDED TUBING @ 3842'. SCREWED ON TO RODS, RESPACED WELL. LOADED AND TEST PUMP TO 500 PSI. HWO. COULD NOT KEEP WELL PUMPING. INSTALLED BACK PRESSURE VALVE. PRESSURED TO 500 PSI, WORKED PUMP AND SET BPV @ 250 PSI TO 200 PSI. WATCHED WELL FOR 1 HOUR. PUMPING OK. SDOWE. WELL PUMPING ON HAND TO BATTERY.

KB	6.00'	6.00'
121 2-3/8" J55 EUE 8RD BB TUBING	3835.57'	3841.57'
2-3/8" STANDARD SEATING NIPPLE	1.10'	3842.67'
RODS		
1-1/4" X 16' POLISHED ROD WITH 1-1/2" LINER	11.00'	
132 X 5/8" RODS	3300.00'	
20 X 7/8" RODS	500.00'	
2.00 X 1.50 X 12.00' RWBC PAP PUMP W/PU SUB	13.00'	

3/14/16

WELL PUMPING TO BATTERY. CLEANED WELLHEAD AND LOCATION. RDMO.