

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30 - 025-36252</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Kaiser-Francis Oil Company		6. State Oil & Gas Lease No. -
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468		7. Lease Name or Unit Agreement Name Cooper 3
4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>3</u> Township <u>20S</u> Range <u>37E</u> NMPM Lea County		8. Well Number 7
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3559 GR		9. OGRID Number 012361
		10. Pool name or Wildcat Monument (Glorieta)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed procedure:

1. Pull rods & tbgs.
2. Set a CIBP above the producing perfs @ 5305'.
3. Load & test plug and casing to 500#.
4. TIH w/tbg & circ the hole w/2% KCI + corrosion inhibitor.
5. Run rods back in the hole & pack off.
6. Conduct official MIT.

Perfs 5315' - 5326'

HOBBS OCD

SEP 11 2017

RECEIVED

Disconnect flowline from well head. Submit well bore diagram w/C103 subsequent.

Spud Date:

Rig Release Date:

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlotte Van Valkenburg TITLE Mgr., Regulatory Compliance DATE 9/11/17

Type or print name Charlotte Van Valkenburg E-mail address: Charlotv@kfoc.net PHONE: 918-491-4314

For State Use Only

APPROVED BY: Marky Brown TITLE AO/II DATE 9/11/2017

Conditions of Approval (if any):

NO PROD REPORTED - 17 MONTHS

MB.