
<ul> <li>(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)</li> <li>1. Type of Well: Oil Well 2. Name of Operator Wishbone Texas Operating Condition</li> <li>3. Address of Operator 10613 W. Sam Houston Pkwy</li> <li>4. Well Location</li> </ul>	IZ20 South St. France         SESanta Fellinm 87         ICES AND FRIORIE ON WELLS         ISALS TO DRILL OR TO DEEPEN OR PLUS         SALS TO DRILL OR TO DEEPEN OR PLUS         Gas Well         Other         mpany LLC         N #400, Houston, Texas 77064	I DIVISION ncis Dr. 7505 UG BACK TO A DR SUCH	WELL API NO. 30-025-09865 30 5. Indicate Type of Lease STATE 6. State Oil & Gas Lease E-2504-4 7. Lease Name or Unit A State H 8. Well Number 2	FEE e No. Agreement Name
Unit Letter H : 2210 Section 2	feet from the North line and 990 fee Township 15S		NMPM	Country Loo
Section 2	11. Elevation <i>(Show whether DR)</i>	0		County Lea
	3604 GL	, 10, 20, 10, 01, 010,		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data         NOTICE OF INTENTION TO:         PERFORM REMEDIAL WORK       PLUG AND ABANDON         TEMPORARILY ABANDON       CHANGE PLANS         PULL OR ALTER CASING       MULTIPLE COMPL         CLOSED-LOOP SYSTEM       OTHER:         OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion.				
	5' on CIBP.	a copy of the daily r	7/A State F 9/16/20	
Spud Date:	Rig Release Da			red T/A. Mulb
I hereby certify that the information			e and belief. t DATE 09/05/2017	
Type or print name Tim Wall E For State Use Only APPROVED BY: Conditions of Approval (if any):	E-mail address: twall@wishboneep.		DATE	
-FF	- Sauce	- nel	aur	



State H #2

7/25/2017

## CELERO ENERGY II, LP Daily Report State H #2 Lea County, NM

## 10/5/07

Day #1. Arrive on location: MIRU Basic Services #1250 PU. Well flowing water. RU Vacuum truck. ND flowlines and master valve. NU BOP. RU SOS Spooler, LD donut Jt. POH with a total of 148 jnts of 2-7/8" 6.5# L80 8rd tbg, 2-7/8" SN, x/o, (1) SD 650 pump – 171 stages, 1 RGS Gas Separator, (2) 66L seals, (1) 40hp/880v/29amp motors rerated to 50hp/952v/34amp, 1 A-well sensor. SI well and SDFWE. NOTES: Send sub pump and switchboard to SOS.





## 10/8/07

Day #2. Arrive on location: RU Rotary Wireline. RIH with a 5-1/2" CIBP, locate collars at 9035', 9067', 9095' & 9126'. Attempt to set CIBP at 9110'. Did not set, POH with setting tool, CIBP had been shot off but did not set. RIH with a 4.375 gauge ring. Tag at 9350', POH with gauge ring. RIH with a 2<sup>nd</sup> CIBP, location collar at 9095'. Set CIBP at 9090'. Immediately well quit flowing water. POH with setting tool. RU dump bailer, RIH and dump 35' cmt on CIBP. RD Rotary Wireline. ND BOP. NU Seaboard WH, RU Key Pump Truck. Pressure casing obtain 30 minutes test at 560 psi. SI well and SDFN.

DWC:

CWC: \$

## 10/9/07

Day #3. Arrive on location: RDPU, move off location. DWC: CWC: CWC: