

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 88410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

HOBBS OCD

SEP 21 2017

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-37435
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 19552
7. Lease Name or Unit Agreement Name North Hobbs Unit (G/SA)
8. Well Number 943
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3660.8' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Occidental Permian Ltd	
3. Address of Operator P.O. Box 4294, Houston, TX 77210	
4. Well Location Unit Letter H : 2470 feet from the North line and 225 feet from the East line Section 19 Township 18S Range 38E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3660.8' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: TA ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU x NDWH x NUBOP.
- POOH 124 jts tbx x ESP equipment.
- RIH 5 1/2" CIBP @ 4162' x dumped 5 sx cmt on top.
- Tagged TOC @ 4127'.
- Ran MIT for TA - Chart attached
- RD x NDBOP x NUWH.

This Approval of Temporary  
Abandonment Expires 8/9/2019

\*\*\*\*\* Well is currently TA'd \*\*\*\*\*

Spud Date: 08/07/17

Rig Release Date: 08/09/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Hood TITLE Regulatory Specialist DATE 09/11/2017

Type or print name April Hood E-mail address: April\_Hood@Oxy.com PHONE: 713-366-5771

For State Use Only

APPROVED BY: Mary Brown TITLE AD/II DATE 9/27/2017

Conditions of Approval (if any):

RBDMS-CHART-✓



PRINTED IN U.S.A.

Graphic Controls LLC  
(6.375 ARC LINE GRAD.)

DATE 8-9-17  
MCI P 0-1000-8-96MIN

32 min -

July 15-19

Power

Start

4

21-1-20

4. 4. 8

1.201

U  
V  
e

At 580#

and 500

743

North Hobbs 943-19 Well Bore Diagram as of September 2017

API # 30-025-37435

