Submit I Copy To Appropriate District	State of New Me	exico		Form C-103	
Office District I - (575) 393-6161 End	Energy, Minerals and Natural Resource			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	NM 88240			WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OI	M 88210 OIL CONSERVATION OF VISION			30-025-41091 5. Indicate Type of Lease	
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr o 2 2011			STATE FEE	
District IV – (505) 476-3460	1220 South St. Francis Dr 0 2 2011 Santa Fe, NM 87505 State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Ranger 12 State		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				-	
1. Type of Well: Oil Well 🗌 Gas Well 🛛 Other		8. Well Number #001			
2. Name of Operator			9. OGRID Number		
Matador Production Company			228937		
3. Address of Operator			10. Pool name or Wildcat		
5400 LBJ Freeway, Suite 1500			Lea; Wolfcamp (Gas)		
Dallas, TX 75240					
4. Well Location					
Unit Letter M_: 660 feet from the South line and 660 feet from the West line					
Section 12 Township 20S Range 35E NMPM County: Lea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,662' Ground Level					
5,002 Ground Lever					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT R					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK					
DOWNHOLE COMMINGLE				P&A R	
OTHER:		OTHER:		_	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
 MIRU PU. Blow well down, ND WH & NU BOP, TOOH & LD tbg, TAC. 					
 Blow well down. ND WH & ND BOP. TOOH & LD tog, TAC. RU swivel package and burn over shoe bit. TIH, drill out/chase CBP's down to 11,690'. Tag CFP @ 11,690'. TOOH w/ tbg and bit. 					
4. TIH and set CIBP @ 11,604'. Spot 25 sx Cl H cmt through tbg. WOC 4 hrs & Tag. TOOH.					
5. TIH and set CIBP @ 9,233'. Spot 25 sx CI H cmt through tbg. WOC 4 hrs & Tag. TOOH.					
 TIH and set CIBP @ 8,582'. Spot 25 sx CI H cmt through tbg. WOC 4 hrs & Tag. Decomposite to the set of 500 and 					
 Pressure test csg to 500 psi. POOH to 5,914' (Shoe Plug). Spot 30 sx Cl C cmt. WOC 4 hrs & Tag. TOOH. 					
9. RU wireline. RIH and perf @ 3,700' (Base of Salt). Sqz w/ 50 sx Cl C cmt. WOC 4 hrs & Tag.					
10. RIH and perf @ 2,110' (Shoe and Top Salt). Sqz w/ 50 sx Cl C cmt . WOC 4 hrs & Tag					
 RIH and perf @ 152'. Circulate CI C cmt to surface inside/outside 7" csg. Cut off wellhead, verify cmt in annulus and install NMOCD marker. *Note: because this well is in the Lessor Prairie Chicken area, the P&A 					
 Cut off wellhead, verify cmt in annulus ar marker plate will be installed 3' below groups 		lote: because this well	is in the Lessor Prairie	Chicken area, the P&A	
Note: Mud laden fluid consisting of 10 ppg brine mixed at a ratio of 25 sx of salt gel per 100 bbls will be placed between all cmt plugs.					
Saud Data: 4/22/2013				OPTO	
Spud Date: 4/22/2013	Rig Release		24 HOURS PRI		
		BEGINNING P	LUGGING OPE	ERA HUNS	
I have been and if that the information above is	mus and a smallete to the h		and hall of		
I hereby certify that the information above is t	rue and complete to the o	est of my knowledge	e and bener.		
SIGNATURE	TITLE EI	igineer	DATE	E <u>9/19/17</u>	
Type or print name <u>Chris Villarreal</u> E-mail address: <u>cvillarreal@matadorresources.com</u> PHONE: <u>972-371-5471</u>					
For State Use Only					
APPROVED BY: Marhuhitaku TITLE Petroleum Engr. Specialist DATE 10/03/2017					
Conditions of Approval (if any):					



