Form 3160-5	OCD Hobbs						
(June 2015)	UNITED STATES EPARTMENT OF THE INTERIOR SUREAU OF LAND MANAGEMENT			OMB		APPROVED O. 1004-0137 muary 31, 2018	
SUNDI	ELLS		5. Lease Serial No. NMLC061873				
Do not use this form for proposals to drill or to re-enter a abandoned well. Use form 3160-3 (APD) for such proposa				OCD	6. If Indian, Allottee o	r Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on pa				2017	7. If Unit or CA/Agree 891005247X	ement, Name and/or No.	
1. Type of Well					8. Well Name and No. COTTON DRAW	UNIT 508H	
Oil Well Gas Well Other Contact: CHANCE BLAND RECEIVE CONTACT: CHANCE BLAND RECEIVED CONTACT: CHANCE BLAND RECEIVED					9. API Well No.		
3a. Address 3b. Phone N 333 WEST SHERIDAN AVENUE Ph: 405-6 OKLAHOMA CITY, OK 73102 Ph: 405-6			. (include area code) 3-9277		10. Field and Pool or Exploratory Area PADUCA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 18 T25S R32E SWSE 540FSL 1670FEL 32.124561 N Lat, 103.711288 W Lon					LEA COUNTY,	NM	
12. CHECK THE	APPROPRIATE BOX(ES)) TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	□ Acidize	□ Acidize □ Deepen □ Proc		Product	ion (Start/Resume)	□ Water Shut-Off	
Subsequent Report	□ Alter Casing	Hydraulic Fracturing				U Well Integrity	
	Casing Repair	_	w Construction	Recomp		🛛 Other	
Final Abandonment Notic	Change Plans		g and Abandon g Back	U Tempor	arily Abandon Disposal		
 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. SUMMARY OF CHANGES: Devon Energy respectfully requests approval for the following changes and additions to the drilling plan: 1. Utilize a spudder rig to pre-set surface casing. 2. Description of Operations 1. Spudder rig contractor Transend Drilling will move in their rig to drill the surface hole section and pre-set surface casing on the Cotton Draw Unit 508H. a. After drilling the surface hole section, the rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations). 							
14. I hereby certify that the foregoi	g is true and correct.		I				
	Electronic Submission For DEVON ENERG mitted to AFMSS for process	Y PRODUCTIO	N COMPAN, sen	t to the Carls	bad		
Name (Printed/Typed) CHANCE BLAND			Title AUTHO	RIZED REF	RESENTATIVE		

A

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Date 09/01/2017

_Approved By_CHRISTOPHER WALLS		Date 09/25/2017				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office Carlsbad					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United						

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** K

(Electronic Submission)

Signature

Additional data for EC transaction #387223 that would not fit on the form

32. Additional remarks, continued

b.Rig will utilize fresh water based mud to drill 17?? surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.

2. The wellhead will be installed and tested once the 13-3/8? surface casing is cut off and the WOC time has been reached.

3.A blind flange with the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.

a.A means for intervention will be maintained while the drilling rig is not over the well.

4.Spudder rig operations is expected to take 8-10 days on a multi well pad 5.The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations. 6.Drilling operation will be performed with the big rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well. a.The BLM will be contacted / notified 24 hours before the big rig moves back on to the pad with the pre-set surface casing.

7.Devon Energy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
8.Once the rig is removed, Devon Energy will secure the wellhead area by placing a guard rail

around the cellar area.