Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter a

abandoned well. Use form 3160-3 (APD) for such proposals

abandoned well. Use form 3160-3 (APD) for such proposals.						THE TAIL	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree NMNM137151	7. If Unit or CA/Agreement, Name and/or No. NMNM137151	
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. MORAB 29-20 FE	8. Well Name and No. MORAB 29-20 FED COM 2H	
Name of Operator Contact: LINDA GOOD     DEVON ENERGY PRODUCTION COMERMAN: linda.good@dvn.com					9. API Well No. 30-025-43775-0	9. API Well No. 30-025-43775-00-X1	
3a. Address 333 WEST SHERIDAN AVENUE OKLAHOMA CITY, OK 73102  3b. Phon Ph: 40:			o. (include area code) 62.6558		10. Field and Pool or E PADUCA	10. Field and Pool or Exploratory Area PADUCA	
4. Location of Well (Footage, Sec., T	11. County		11. County or Parish, S	State			
Sec 29 T25S R32E SENW 24 32.101864 N Lat, 103.697334	LEA COUNTY, NM			NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION				N		
Notice of Intent	☐ Acidize	Acidize		☐ Proc	luction (Start/Resume)	☐ Water Shut-Off	
☑ Notice of Intent	☐ Alter Casing	☐ Hydr	raulic Fracturin	g Rec	amation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Rec	omplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tem	porarily Abandon	Change to Original A	
	☐ Convert to Injection	☐ Plug Back ☐ Water		er Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1. SUMMARY OF CHANGES:  Devon Energy respectfully requests approval for the following changes and additions to the drilling plan:  1. Utilize a spudder rig to pre-set surface casing.  2. Description of Operations  1. Spudder rig contractor Transend Drilling will move in their rig to drill the surface hole section and pre-set surface casing on the Morab 29-20 Fed Com 2H.  2. After drilling the surface hole section, the rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).  3. Rig will utilize fresh water based mud to drill 17?" surface hole to TD.							
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #387896 verified by the BLM Well Information System  For DEVON ENERGY PRODUCTION COMPAN, sent to the Hobbs  Committed to AFMSS for processing by DUNCAN WHITLOCK on 10/10/2017 (18DW0003SE)  Name (Printed/Typed) LINDA GOOD  Title REGULATORY SPECIALIST							
Signature (Electronic Submission)		Date 09/07	/2017				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE 1 0 2017							
Approved By mustafa _	Hague		Title	DOMETH	J OF LAND MANAGEMEN	Date 10-10-201	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office C	FO	RLSBAD FIELD OFFICE			

## Additional data for EC transaction #387896 that would not fit on the form

## 32. Additional remarks, continued

2. The wellhead will be installed and tested once the 13-3/8" surface casing is cut off and the WOC time has been reached.

3. A blind flange with the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.

a. A means for intervention will be maintained while the drilling rig is not over the well.

a. A means for intervention will be maintained while the drilling rig is not over the well.

4. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.

5. Drilling operation will be performed with the big rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well.

a. The BLM will be contacted / notified 24 hours before the big rig moves back on to the pad with the pre-set surface casing.

6. Devon Energy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.

7. Once the rig is removed, Devon Energy will secure the wellhead area by placing a guard rail

around the cellar area.