Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-005-61766
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease FEDERAL
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		NMNM - 032335
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIE	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	ANTELOPE FEDERAL
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other		8. Well Number Z
Name of Operator State of New Mexico formerly	McKay Oil Corp	9. OGRID Number 14424
3. Address of Operator		10. Pool name or Wildcat
1625 N. French Drive Hobbs	s, NM 88240	Pecos Slope; Abo, West (Gas)
4. Well Location Unit Letter J: 1980 feet from the South line and 1980 feet from the EAST line		
Section 29 Township 45 Range 2ZE NMPM County CHAVES 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	11. Elevation (Snow whether DR, RRB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	□ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
SEE ATTACHED PROCEDURE & SCHEMATICS		
SEE III INCHED I ROCEDORE & SCHEWITTICS		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Mal Wildlate TITLE Petroleum Engr. Specialist DATE 8/22/2017		
Type or print name Mark Whitaker E-mail address: marka.whitaker@state.nm.us PHONE: 575-393-6161		
For State Use Only Madeud Struck 10 / 12017		
APPROVED BY: DATE TITLE DATE		
Conditions of Approval (if any):		

McKay Oil Corp Antelope Federal No. 2 30-005-61766 UL – J, Sec. 29, T4S, R22E 1980' FSL & 1980' FEL BLM Serial #: NM – 032335

7 5/8" 26.4# @ 1467' w/ 1300 sx cmt 4 1/2" 10.5# @ 3592' w/ 270 sx cmt Top Perforation 3066'

- 1. MIRU. POOH w/ production equipment.
- 2. Set CIBP at 2966'. Circulate hole with mud laden fluid. Pressure test casing to 500 psi. Spot 25 sx cement on CIBP.
- 3. Perf @1517'. Sqz w/ 45 sx. WOC. Tag at 1417' or better.
- 4. Perf @100'. Circulate cement to surface inside/outside 4 ½" casing.
- 5. Cut off wellhead 3' below ground level and verify cement to surface all strings.
- 6. Install below ground P&A marker. Photos should be taken prior to and after welding on plate. Record GPS reading. BLM should be notified prior to cut off so it can be witnessed.

NOTES: Mud laden fluid consists of fresh water with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

CURRENT 30-005-61766


McKay Oil Corp Antelope Federal #2

7 5/8" 26.4# @ 1467' w/ 1300 sx. Circ cmt

Top perf 3066'

4 1/2" 10.5# @ 3592' w/ 270 sx. TOC unknown

McKay Oil Corp Antelope Federal #2



CUT OFF WELLHEAD 3' BELOW GL,
VERIFY CEMENT, & INSTALL BELOW GROUND
MARKER. TAKE PHOTO & GPS READINGS
PERF @ 100'. CIRC CMT TO SURFACE

7 5/8" 26.4# @ 1467'

PERF @ 1517'. SQZ W/ 45 SX. WOC & TAG.

PRESSURE TEST CASING CIRCULATE MUD LADEN FLUID

SET CIBP AT 2966'. CAP WITH 25 SX

Top Perf 3066' 4 1/2 "10.5# @ 3592'