Form 3160-5 (June 2015)

(Instructions on page 2)


UNITED STATES DEPARTMENT OF THE INTERIOR NMOCD BUREAU OF LAND MANAGEMENT Hobbs


FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM105560


	TIONOR
SUNDRY NOTICES AND REPORTS ON V	VELLS
Do not use this form for proposals to drill or to abandoned well. Use form 3160-3 (APD) for such	re-enter an
abandoned well. Use form 3160-3 (APD) for such	proposals


abandoned well. Use form 3100-3 (APD) for such proposals			6. If Indian, Allottee of	r Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 3			7. If Unit or CA/Agree	ment, Name and/or	No.	
1. Type of Well		RECE		8. Well Name and No. RED HILLS WEST	LINIT 18H	,
Oil Well Gas Well Oth 2. Name of Operator		(IE LATHAN		9. API Well No.	01411 1011	
MEWBOURNE OIL COMPAN	Y E-Mail: jlathan@mewbo			30-015-43913		
3a. Address PO BOX 5270 HOBBS, NM 88241		Phone No. (include area code) 575-393-5905		10. Field and Pool or Exploratory Area WOLFCAMP		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish, S	State	
Sec 8 T26S R32E Mer NMP S	WSW 150FSL 330FWL	/		LEA COUNTY, I	NM	×
12. CHECK THE AF	PROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-	Off
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclam	ation	☐ Well Integri	ty
☑ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomp	olete		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	-	arily Abandon	well Spud	
13. Describe Proposed or Completed Ope	Convert to Injection	☐ Plug Back	□ Water I			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 09/10/2017MI & spud 17 1/2" hole. TD'd hole @ 1115'. Ran 1105' of 13 3/8" 54.5# J55 ST&C csg. Cemented with 750 sks Class C w/additives. Mixed @ 13.5 #/g w/ 1.74 yd. Plug down @ 11:30 p.m. 09/11/17. Circ 325 sks of cmt to the pit. Tested BOPE to 10000# & Annular to 5000#. Tested standpipe & mud lines to the pumps to 5000#. At 12:45 P.M. 09/13/17, tested casing to 1500# for 30 minutes, held OK. Drilled out with 12 1/4" bit. FIT test to EMW of 10.5 PPG Chart & Schematic attached. Bond on file: NM1693 nationwide & NMB000919						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #390648 verified by the BLM Well Information System For MEWBOURNE OIL COMPANY, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANCHEZ on 10/11/2017 () Name (Printed/Typed) JACKIE LATHAN Title AUTHORIZED REPRESENTATIVE						
Name (Printed/Typed) JACKIE L	ATHAN	Title AUTHOR	AO.C.F	PIFD FOR RE	CORA	
Signature (Electronic S	submission)	Date 10/03/20	017			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE 2017						
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent is	uitable title to those rights in the subject operations thereon. U.S.C. Section 1212, make it a crime	ct lease Office for any person knowingly and		ARLSBAD FIELD OF	7/	<u></u>
Sacro any raise, neutrous of fraudulent s	mentents of representations as to any	manufacture in the particular doll.				


** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **











MAN WELDING SERVICES, INC.

Company Mewhourne	Date_ 9-12	-17
Lease Red Hills West Unit #018H	County e3	NM
Drilling Contractor Herson 231	_Plug & Drill Pipe Size_	4/2 IF/CET-39
Accumulator Pressure: 3000 Manifold	Pressure: 1500	Annular Pressure: 1000

Accumulator Function Test - OO&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 1400 psi. Test Fails if pressure is lower than required.
 - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}
 - 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 - a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop psi. Test fails if pressure drops below minimum.
- Minimum: a.{700 psi for a 1500 psi system} b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time 1.27. Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system}
 b. {1200 psi for a 2000 & 3000 psi system}



Casing

WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Lovington, NM • 575-396-4540

Pg. 1 of 1

W.

Drilling Contractor: Port # OI 44 Plug Size & Type: Required BOP: Installed BOP: * Check Valve Must Be Open/Disabled To Test Kill Line Valves *Appropriate Casing Valve Must Be Open During BOP Test Dart Valve nhanha #2 Stand Pipe Valve Kelly/ #24 Annular #15 Top Drive #22 #23 TIW Valve Pipe Rams #12 IBOP #18 #17 Blind Rams #13 #8B Manual Mud Gauge IBOP Pump Valve #21 Valve Pump Valve #20 #16 #11 #10 #9 20-617 #25 Pipe Rams #14 Super Choke

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
1	Truck Test	10-10	200	10,00	P3:5
2	1,2,6,5B,8	10-10	250	10,00	Pass
3	25,26,6,5B,8	Bump		10,000	Pars 5.
4	3,4,5,8	10-19	250	10,000	Pass
6	19 45 IF	10-10	250	5,000	Pass
б	18 45 IF	10.10	250	5000	Pa57
7	18 (ET.39	19-10	25a	5000	Pass
8	19 (ET.39	10.10	250	5000	Pass
9	120,21,22,23	10-10	250	500	Pass
10	17	19-10	250	5000	P255
11/	116	10-10	0-		Pass
12	15,9,3,45,8B	19.19		5000	Pass 45 IF
13	12,9,3,4,5,8B	10-19			Pass 4% IF
-14	12,10,8	10.10	250	10,000	Pass 4/2 IF
15	1 14	19-10	250	10,000	Pass- 45 IF
16	13,3,4,5,10	10-10	250	19,000	
17		10-10	0-0	10,000	
18	12.11.7	10-10	250	10,000	Rass CET-39