

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-31957
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Ellen Sims
8. Well Number 9
9. OGRID Number 269184
10. Pool name or Wildcat West Blinebry
11. Elevation (Show whether DR, RKB, RT, GR, etc.) KB-3343'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Ernmar Investments, Inc.

3. Address of Operator
P.O. Box 6492, Edmond, OK 73083-6492

4. Well Location

Unit Letter B 990 feet from the North line and 1651 feet from the East line
Section 3 Township 23S Range 37E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER ☒
Perf & Stimulate Add't Pay

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MI rig on 8/9/17.
2. Clean out 5 1/2" csg to 6650' & circ'd hole clean w/ treated wtr.
3. TOH & LD tools.
4. RU wireline & perforated 6441'-43', 6486'-88', 6531'-33', 6540'-42'. & 6548'-52' for a total of 17 holes.
5. TIH w/ pkr on 2 7/8" tbg & set pkr @ 6363'.
6. Acidize & frac perfs 6441'-6552' w/ 1500 gals 15% acid, 12,000 gals gelled wtr + 12,000# 20/40 sd.
7. TOH w/ pkr.
8. TIH w/ bit & cleaned out sd fill to 6588'.
9. TIH w/ pkr on 2 7/8" tbg & set @ 5709'.
10. TIH w/ 2 1/16" tbg to 6407'.
11. TIH w/ pump on 3/4" rods.
12. Move rig out & returned well to production 9-11-17.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross TITLE President DATE 11/16/17

Type or print name E. L. Buttross E-mail address: ernie@ernmar.com PHONE: 405-478-754

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 11/22/17
Conditions of Approval (if any):