

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD

Hobbs
HOBBS OGD

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

DEC 05 2017

SUBMIT IN TRIPLICATE - Other instructions on page 2

RECEIVED

5. Lease Serial No. NMNM56265
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No. LEA SOUTH FED COM 2BS 10H ✓
9. API Well No. 30-025-43409
10. Field and Pool or Exploratory Area WILDCAT; BONE SPRINGS
11. County or Parish, State EDDY COUNTY, NM

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator CHISHOLM ENERGY PRODUCING, LLC Contact: BETTIE WATSON Email: bettie@watsonreg.com	
3a. Address 801 CHERRY STREET, SUITE 1200-UNIT 20 FORT WORTH, TX 76102	3b. Phone No. (include area code) Ph: 972-979-0132
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 25 T20S R34E SWSW 330FSL 2130FWL	

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Hydraulic Fracturing
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recombine
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Drilling Operations

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

pending change of operator

PSI Reporting:

07/09/17 Surface csg: 13-3/8 1500 psi for 30 min. Test OK.
07/17/17 Intermediate csg: 9-5/8 1500 psi for 30 min. Test OK.
08/25/17 Prod csg: 5-1/2 8500 psi for 30 min. Test OK.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #394248 verified by the BLM Well Information System For CHISHOLM ENERGY PRODUCING, LLC, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANCHEZ on 11/08/2017 ()	
Name (Printed/Typed) BETTIE WATSON	Title AGENT
Signature (Electronic Submission)	Date 11/07/2017
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved By _____	Title _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office _____

ACCEPTED FOR RECORD

NOV 8 2017

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****

KZ