

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-62482 ✓
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease FEDERAL STATE FREE
2. Name of Operator State of New Mexico formerly McKay Oil Corp		6. State Oil & Gas Lease No Federal Lease NMNM-032312
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name West Fork Unit ✓
4. Well Location Unit Letter <u>M</u> : <u>990</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>7</u> Township <u>5S</u> Range <u>22E</u> NMPM Chaves County ✓		8. Well Number 002 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 14424 ✓
		10. Pool name or Wildcat Pecos Slope Abo, West (Gas) ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO
PERFORM REMEDIAL WORK ☐ **INT TO PA**
TEMPORARILY ABANDON ☐ **P&A NR**
PULL OR ALTER CASING ☐ **P&A R** 7m
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A XX
CASING/CEMENT JOB ☐

OTHER: _____

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: M. Whitaker TITLE P.E.S. DATE 12/26/2017

Conditions of Approval (if any):

mw

Plugging Report
West Fork Unit #2
Lat: 33.8844509456 Lon: -104.681624287

12/8/2017 Worked to move larger rocks off of the road to location. Moved in equipment and set matting board. Located and tested the anchors. Rigged up and dug out cellar. Plumbed in wellhead to the tank and started to blow down the well.

12/11/2017 Killed the well and installed BOP. POOH with 126 joints of tubing. Set CIBP at 2740'. There was a collar at 2735'. Circulated MLF and tested casing to 550#. Casing good. Spotted 25 sx cement on top of CIBP and POOH. Perforated 4 1/2" casing at 1006'. Established circulation and laid down remaining pipe. SION

12/12/2017 Pumped cement down the 4 1/2" casing to the perfs at 1006' and up the annulus to surface. Took 270 sx to get cement to surface. Rigged down and dug out the cellar. Had to use a jack hammer to clear the rock from around the 8 5/8" casing to get low enough to cut off. Cut off wellhead and filled up both strings with less than 1 sack of cement. Installed the marker, cut off anchors, and cleaned the pit.

NOTE: Found document in well file of top perf
at 2834'
Moved CIBP setting to 2740' mw