

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26307
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <u>Brine Well</u>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator <u>PAB Services DBA SALTY Dog INC</u>		6. State Oil & Gas Lease No. 25087
3. Address of Operator <u>PO Box 190 Lubbock Texas 79408</u>		7. Lease Name or Unit Agreement Name <u>Brine Supply Well</u>
4. Well Location Unit Letter <u>J</u> : <u>1980</u> feet from the <u>SOUTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>5</u> Township <u>19S</u> Range <u>36E</u> NMPM <u>LEA</u> County		8. Well Number <u>801</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <u>184208</u>
		10. Pool name or Wildcat <u>BSW + SALADO</u>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Rig up pulling Unit
Pull tubing
Replace Damaged Tubing
go back into hole

C.O.A. - CHART TEST -
RUN PK 1800' +/- TEST
CASING TO 300' + FOR
30 mins.
OR DO CAVERN TEST OF
300' + FOR 4 HOURS.

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

1-9-18

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim Sayre

TITLE MANAGER

DATE 1-8-18

Type or print name JIM SAYRE

E-mail address: jim@hstandardenergy.com

PHONE: 575-393-8352

For State Use Only

APPROVED BY:

Accepted for Record Only

DATE

Conditions of Approval (if any):

MS Brown 1/8/2018