

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO. 30-025-28411 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit |
| 8. Well Number 142 Z |
| 9. OGRID Number 157984 |
| 10. Pool name or Wildcat Hobbs (G/SA) |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3635 KB |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ Injector

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
PO Box 4294 Houston, TX 77210

4. Well Location
Unit Letter _____ M : 1250 feet from the _____ S line and 185 feet from the _____ W line
Section 33 Township 18S Range 38E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU x NDWH x NUBOP. POOH 125 jts tbg x pkr x on/off tool. RIH 4 3/4" bit x tagged TD @ 4295'.

Shot new perfts 4095' - 4252'. Ran acid job w/ 1900 gals 15% NEFE HCL x flushed w/ 1700 gals BW.

RIH 5 1/2" rbp @ 4205' x packer @ 4150' x ran acid job 4152'-4198' w/ 1500 gals 15% NEFE x 700 lbs rock salt.

Flushed w/ 100 bbls FW. RIH on/off tool x pkr @ 3975' x 127 jts tbg @ 3968'. Ran MIT chart - Chart attached

**** Well is currently on injection****

Spud Date: 11/13/17

Rig Release Date: 11/17/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Hood TITLE Regulatory Specialist DATE 01/04/18

Type or print name April Hood E-mail address: April_Hood@Oxy.com PHONE: 713-366-5771

For State Use Only

APPROVED BY: Maxey Brown TITLE AO/II DATE 1/25/2018

Conditions of Approval (if any):

RBDMS - CHART - ✓

START

Graphic Controls Inc.
(6.375 ARC LINE GRAD.)

NH0 33/142
DATE 11-17-17
MCI P 0-1000-8-96MIN

32 min

End 560 #

Start 560 #

60 min

1000 #

1000 # 48 d2

2-8-17

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

33-18-332

Start
Foot workover
N.H. G. 5/14 # 1422

Handwritten notes:
Hester Rev. blank
May Johnson - OED
33-18-332

End

PRINTED IN U.S.A.