Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-44012
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe VM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	The wife	39819
87505	3 /CV	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
	DPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PLICATION FOR PERMIT" (FORM C-101) FOR SUCH	RANGER 33 STATE COM
PROPOSALS.)	TELECATION TON TENNIT (TONNIC-101) TON SOCI	0.337.11371
1. Type of Well: Oil Well X	Gas Well Other	8. Well Number 123H
2. Name of Operator Matador	Production Company	9. OGRID Number 228937
D. Itaaress of Operator	00 LBJ Freeway	10. Pool name or Wildcat
	E 1500 Ilas, TX 75240	GRAMA RIDGE;BONE SPRING, NORTH
4. Well Location		
Unit Letter B : 265 feet from the NORTH line and 2125 feet from the EAST line		
Section 33 Township 20S Range 35E NMPM County LEA		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
	3697' GR	是是1963年200月程。1965年
12. Chec	k Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. 01100	A rippropriate Box to indicate rataire of riotice,	report of other bata
NOTICE OF	INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	□ PLUG AND ABANDON □ REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐ COMMENCE DRI	
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐ CASING/CEMENT	T JOB
CLOSED-LOOP SYSTEM		
OTUED:	I I OTHER Perfora	to tracture tract produce
OTHER:		te, fracture treat, produce
13. Describe proposed or co	ompleted operations. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date
Describe proposed or co of starting any proposed	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date
13. Describe proposed or co	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date
Describe proposed or co of starting any proposed	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of
13. Describe proposed or co of starting any proposed proposed completion or	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 -	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 min	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 -	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Jubing Reco	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. 'w/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Jubing Reco	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Jubing Reco	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. 'w/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17 Spud Date: 9/25/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17 Spud Date: 9/25/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Jubing Reco	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17 Spud Date: 9/25/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/15/17 11/22/17 Spud Date: 9/25/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1 ion above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. I w/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/22/17 Spud Date: 9/25/17	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. W/ 12,258,550 lbs sand in 18 stages.
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/15/17 11/22/17 Spud Date: 9/25/17 I hereby certify that the informat SIGNATURE Character of Starting any proposed or co of starting and starting any proposed or co of starting and starting and starting and starting and starting and starting any proposed or co of starting and starting and starting and starting	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1 ion above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. I w/ 12,258,550 lbs sand in 18 stages. 5/17 e and belief. DATE 01/25/17
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/15/17 11/22/17 Spud Date: 9/25/17 I hereby certify that the informat SIGNATURE Type or print name Ava Monroe	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1 ion above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. I w/ 12,258,550 lbs sand in 18 stages. 5/17 e and belief. DATE 01/25/17
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/15/17 11/22/17 Spud Date: 9/25/17 I hereby certify that the informat SIGNATURE Character of Starting any proposed or co of starting and starting any proposed or co of starting and starting and starting and starting and starting and starting any proposed or co of starting and starting and starting and starting	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1 ion above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. I w/ 12,258,550 lbs sand in 18 stages. 5/17 e and belief. DATE 01/25/17 Tresources.com PHONE: 972-371-5218
13. Describe proposed or co of starting any proposed proposed completion or 11/02/17 - 11/13/17 - 11/15/17 11/15/17 11/22/17 Spud Date: 9/25/17 I hereby certify that the informat SIGNATURE Type or print name Ava Monroe	ompleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. Open well to perform csg test to 5,000 psi for 30 mir Perforate and fracture treat BS from 10919' - 15305 Mill plugs. Open well to flowback to recover load water. Well begins to produce. Rig Release Date: 10/1 ion above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of in. Test good. I w/ 12,258,550 lbs sand in 18 stages. 5/17 e and belief. DATE 01/25/17