Office	State of New Mexico	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 District IV – (505) 476-3460 Santa Fe, NM 87505  Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION South St. Francis Dr. Santa Fe, NM 87505		Revised August 1, 2011 WELL API NO.
		30-025-26187
		5. Indicate Type of Lease
District IV – (505) 476-3460  1220 S. St. Francis Dr., Santa Fe, NM		STATE FEE  6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Long Name of Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name
PROPOSALS.)		Shell Groebli  8. Well Number 001
Type of Well: Oil Well    Gas Well Other      Name of Operator		9. OGRID Number
John R Stearns dba Stearns		21566
3. Address of Operator		10. Pool name or Wildcat
HC65 Box 988, Crossroads, NM 88114		Flying M; San Andres
4. Well Location  Unit Letter B: 525 feet from the North line and 1840 feet from the East line		
Section 30 Township 9S Range 33E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK [  TEMPORARILY ABANDON [ INT TO PA		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE John R Straum TITLE OWNER Operator DATE 02/05/2018		
Type or print name John R. Stearns E-mail address: John bobster NSE Gol. Co. PHONE: 525-691-5019		
APPROVED BY: Mah What TITLE P.E.S,  Conditions of Approval (if any):		
Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent		

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By Ol-09-2019

## Plugging Procedures Shell Groebli #1

1/5/2018 Move in and rig up.

1/8/2018 Laid down rods and tally OOH with tubing. Made a scraper run to 4250'.

1/9/2018 POOH with scraper and set CIBP at 4218'. Circulate MLF and tested casing to 600#. Casing good. Spot 25 sx cement on top of CIBP. POOH to 2401' and spot 40 sx cement. POOH and SION.

1/10/2018 RIH and tagged cement at 1534'. Circulated cement to surface from 574' with 40 sx. Rigged down.

1/15/2018 Cut off wellhead and filled up both string to surface with less than 1 sack of cement. Installed below ground marker and filled in the cellar.

## **Marker Location:**

Lat: 33.5098451037 Lon: -103.60434979