Submit 1 Copy To Appropriate District Office	State of New Me	exico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-023-43041
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505	CES AND REPORTS ON WELLS		7 Lanca Nama on Linit Agreement Nama
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			South Hoods (d/SA) Olin
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injector		8. Well Number: 24-657	
Type of Well: Oil Well Gas Well Other; Injector Name of Operator		9. OGRID Number: 157984	
Occidental Permian Ltd.			9. OGRID Nulliber, 137984
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)	
HCR I Box 90 Denver City, TX 79323			
4. Well Location			
Unit Letter B : 160 feet from the North line and 2269 feet from the East line			
Section 24 Township 18S Range 37E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3674' (GL)		
12. Check A	Appropriate Box to Indicate N	lature of Notice,	Report or Other Data
NOTICE OF IN	TENTION TO		CECUENT REPORT OF
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORL TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI			
TEMPORARILY ABANDON			200 April 1980 1980 1980 1980 1980 1980 1980 1980
DOWNHOLE COMMINGLE	MOLTIFLE COMPL	CASING/CEIVIEN	1308
DOWNINGLE COMMINGLE			
OTHER: Initial Completion		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or rec	ompletion.		
1. MIRU PU.			I as we also to use
During this procedure we plan to dee			
3. RIH and set CIBP w/5' of cement @ 4482' to isolate Zone 31. the closed-loop			loop system with a steel
4. RIH with injection equipment and perform MIT. tank and haul contents to			aul contents to the required
5. RDMO PU. disposal per ODC Rule 19.15.17			
Turn well to injection.			
Spud Date:	Rig Release Da	ate:	
Spau Date.	Rig Release Da	atc.	
I hereby certify that the information	above is true and complete to the b	est of my knowledg	e and belief.
Thereby county and the information	-	out or my mile wiedg	s and other.
SIGNATURE Mil Ne			1.2 111
SIGNATURE MILL THE	TITLE Pol.	DATE 3	112/18
T Piels Beere	E mail addres		DUONE: 712 215 7652
Type or print nameRick Reeves E-mail address rick reeves@oxy.com_ PHONE: _713-215-7653 For State Use Only			
A I	18.	10/	2/ /- 2/0
APPROVED BY: Majey & STOWATLE AO/II DATE 3/12/2018			
Conditions of Approval (if any):			
			C. O. A
Condition of Approval: notify SUBMIT WELLBORE			
TAGRAM IN TITH			DINGRAM WITH
OCD Hobbs office 24 hours			
prior of running MIT Test & Chart SUBSEQUENT C-103.			
production of the state of the			
W. Paris and Control of the Control		as med the core	

mb