مر بهر	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals. B 2018 SUBMIT IN TRIPLICATE - Other instructions on page 2			5. Lease Serial No.	APPROVED 0. 1004-0137 Inuary 31, 2018
ALC:				NMLC061869 6. If Indian, Allottee o	r Tribe Name
	SUBMITIN	7. If Unit or CA/Agree NMNM137151	ement, Name and/or No.		
	1. Type of Well	8. Well Name and No.	EDERAL COM 1H		
	2. Name of Operator DEVON ENERGY PRODUC	9. API Well No. 30-025-43176-0	00-X1		
	3a. Address 6488 SEVEN RIVERS HIGHWAY ARTESIA, NM 88211		30 Phone No. (include area code) Ph: 405.552.6558	10. Field and Pool or I	Exploratory Area 3235G-LWR BONE SPF
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description		n)	11. County or Parish,	State
	Sec 30 T25S R32E Lot 2 2575FNL 660FWL			LEA COUNTY,	NM
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION	TYPE OF ACTION			
	□ Notice of Intent	□ Acidize	Deepen	□ Production (Start/Resume)	□ Water Shut-Off
	Subsequent Report	Alter Casing	Hydraulic Fracturing	□ Reclamation	U Well Integrity
	☐ Final Abandonment Notice	Casing Repair Change Plans	New ConstructionPlug and Abandon	Recomplete Temporarily Abandon	Other
		Convert to Injection		□ Water Disposal	
	Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Upon review of the CBL, the TOC does not meet COA requirements. As per the COA the TOC needs to be 4130', UltraView Cement Evaluation Log shows the TOC to be 4475'. The intermediate shoe is at 4330'. After discovering the low TOC on the cement evaluation log we pressure tested the 5-1/2"x9-5/8" annulus to 550 psi. The pressure held steady with minimal bleed off on each test indicating that we potentially have some lightweight cement tied back into the intermediate casing. The frac date is scheduled for 10/18 so we would like to request variance from the COA and go ahead and complete the well then put on production. In addition, during the frac job we will tie into the 5-1/2"x9-5/8" annulus, install a pressure test at 11500 psi. The pressure will be monitored and recorded at all times. Following the frac job we will tie into the 5-1/2"x9-5/8" annulus and make a second attempt at establishing injection. If we are able to establish injection, a Bradenhead squeeze will				
	14. 1 hereby certify that the foregoing is true and correct. Electronic Submission #392135 verified by the BLM Well Information System For DEVON ENERGY PRODUCTION COM LP, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 11/09/2017 (18DLM0067SE)				
	Name (Printed/Typed) LINDA G	OOD	Title REGUL	ATORY COMPLIANCE SPECIA	ALI
	Signature (Electronic	Submission)	Date 10/17/2	017	5
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
	Approved By ACCEPTED		ZOTA STE TitlePETROLE	EVENS UM ENGINEER	Date 03/05/2018
	Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Hobbs				
	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				
	(Instructions on page 2) ** BLM REVISED **				
MDB/000 3/19/2018					

Additional data for EC transaction #392135 that would not fit on the form where the strangest

32 Additional remarks, continued EPORTE

PNI J.

32. Ald danastensa Server and the state


36

state dril. 2. to re er performed to remediate the low TOC. If we are unable to establish injection we will monitor the re 5-1/2"x9-5/8" annulus for the life of the well via SCADA with alarms set.

Attached is the test chart from the 5-1/2"x9-5/8" annulus pressure test.

The UltraView Log is too large to attach, so I will send via file sharing application for review.

*1. 11 th max 1 1



1