

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-041-20823
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name COOK
8. Well Number 001
9. OGRID Number 263940
10. Pool name or Wildcat TULE MONTOYA;PENN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4359 GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
SOVEREIGN EAGLE LLC

3. Address of Operator  
PO BOX 968, ROSWELL, NM 88202-0968

4. Well Location

Unit Letter B : 330 feet from the NORTH line and 1980 feet from the EAST line  
Section 34 Township 2S Range 29E NMP County ROOSEVELT

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☒  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT

REMEDIAL WORK  
COMMENCE DRILLING OPERATIONS  
CASING/CEMENT JOB  
OTHER: ☐  
INT TO P&A P&M  
P&A NR  
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PROPOSE TO PLUG AND ABANDON:

1. SET CAST IRON BRIDGE PLUG AT 7075' ABOVE MONTOYA PERFS 7104-7116 AND DUMP 35' OF CEMENT ON IT.
2. CANYON PERFS 6853-7064 . Squeeze perfs with 35 sx and leave top of cement at 6753'. WOC & TAG Load hole with mud laden fluids.
3. TOP OF CEMENT behind 5 1/2" casing is 6034'. Perf 4 squeeze holes at 4500' and squeeze 35 sacks under a packer into squeeze perfs and leave 100' of cement inside casing. WOC & TAG.
4. 8 5/8" casing shoe at 2119'. Perf 2169' and squeeze holes with 35 sx under a packer into squeeze perfs and leave 100' of cement inside casing. WOC & TAG. at 2069' OR BETTER
5. 13 3/8" casing shoe at 322'. Perf 372; squeeze holes with cement until cement circulates leaving casing full of cement.
6. NIPPLE DOWN WELLHEAD AND SET CEMENT PLUG AT 60' to SURFACE, cut off wellhead 3' below ground level, verify cement to surface, INSTALL DRY HOLE MARKER AND CLEAN LOCATION.

NOTIFY OCD 24 HOURS PRIOR TO  
BEGINNING PLUGGING OPERATIONS

Release Date:

C103 INTENT TO P&A EXPIRES

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul Ragdale TITLE OPERATIONS MANAGER DATE 03/08/18

Type or print name PAUL RAGSDALE E-mail address: pragsdale@stratanm.com PHONE: 575-622-1127 ext 18

For State Use Only

APPROVED BY: Mark Whitman TITLE Petroleum Engr. Specialist DATE 03/20/2018

Conditions of Approval (if any):



Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87404  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name COOK
2. Name of Operator SOVEREIGN EAGLE LLC	8. Well Number 001
3. Address of Operator PO BOX 968, ROSWELL, NM 88202-0968	9. OGRID Number 263940
4. Well Location Unit Letter <u>B</u> : <u>330</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>34</u> Township <u>2S</u> Range <u>29E</u> NMP County <u>ROOSEVELT</u>	10. Pool name or Wildcat TULE MONTOYA;PENN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4359 GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT

REMEDIAL WORK  
COMMENCE DRILLING OPNS  
CASING/CEMENT JOB  
OTHER: ☐  
INT TO PA PM.X  
P&A NR  
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

③ CIRC MUD LADEN FLUIDS + PRESSURE TEST CASING

PROPOSE TO PLUG AND ABANDON:

- ① SET CAST IRON BRIDGE PLUG AT 7075' ABOVE MONTOYA PERFS 7104-7116 AND DUMP 35' OF CEMENT ON IT.
- ② SET CAST IRON BRIDGE PLUG AT 6825' ABOVE CANYON PERFS 6853-7064 AND DUMP 35' CEMENT ON IT.
- ③ CUT 5 1/2" CASING OFF AT 5950' AND PULL 5 1/2" CASING.
- ④ SET 100' CEMENT PLUG IN OPEN HOLE FROM 5900-6000' ABOVE WOLFCAMP TOP IN AND OUT OF 5 1/2" CASING STUB. TOC @ 6030' BY CBL. (35 SX) WOLC + TAG
- ⑤ SET 100' CEMENT PLUG IN OPEN HOLE FROM 4000' - 4100'. (35 SX) WOLC + TAG
- ⑥ SET 100' CEMENT PLUG IN OPEN HOLE FROM 2050' - 2150'. (35 SX) WOLC + TAG
- ⑦ SET 100' CEMENT PLUG IN OPEN HOLE FROM 275' - 375'. (35 SX) WOLC + TAG
- ⑧ NIPPLE DOWN WELLHEAD AND SET 10 SACK CEMENT PLUG AT SURFACE, INSTALL DRY HOLE MARKER AND CLEAN LOCATION. 60' TO CUT OFF WELLHEAD 3' BELOW GROUND LEVEL, VERIFY CMT TO SURFACE

Spud Date: 4/22/88

NOTIFY OCD 24 HOURS PRIOR TO  
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul Ragdale TITLE OPERATIONS MANAGER DATE 08/15/17

Type or print name PAUL RAGSDALE E-mail address: pragsdale@stratanm.com PHONE: 575-622-1127 ext 18  
For State Use Only

APPROVED BY: Mark Whitman TITLE Petroleum Engr. Specialist DATE 08/21/2017  
Conditions of Approval (if any):

[illegible]