Submit 3 Copies To Appropriate District			Form C-103		
Office State of New M			October 25, 2005		
District I Energy, Minerals and Nat 1625 N. French Dr., Hobbs, NM 88240	ural Resources WE	WELL API NO. 30-025-26071			
			20071		
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 BBS DECONSERVATIO	5.1	Indicate Type of Lease			
1000 Rip Brazos Rd. Aztec, NM 87410	incis Dr.	STATE 🗹	FEE 🗌 📝		
District IV 1220 S. St. Francis Dr., Santa Fe, NM	7505 6.8	State Oil & Gas Lease			
87505		BO-1	557		
SUNDRY NOTICES AND REPORTS ON WELLS		Lease Name or Unit Ag	greement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		State "C"	Tract 13 🗸		
PROPOSALS.) 1. Type of Well: Oil Well 🗹 Gas Well 🗌 Other		Well Number 10	/		
2. Name of Operator		OGRID Number	,		
Apache Corporation		87	3		
3. Address of Operator		Pool Name			
303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79 4. Well Location	705	Blinebry O&	G (OII)6660		
	N line and	1980 feet from the	W line		
Section 36 Township 21S Range		IPM (County Lea /		
11. Elevation (Show whether DR, R 3369'(
12. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB Image: Commence of the second s					
			V		
OTHER: Location is ready for OCD inspection after P&A Image: Constraint of the operator is pready for OCD inspection after P&A					
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 					
A steel marker at least 4" in diameter and at least 4' above ground level has be					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and					
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
 If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed 					
from the lease and well location.					
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)					
All other environmental concrens have been addressed as per OCD rules.					
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.					
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.					
Inspection has to be made to a P&A location because it does not meet the chte	na above, a penaity may i	be assessed.			
SIGNATURE Such Burks TITLE S	Sr. Reclamation Fore	man DATE	3/15/18		
	nn.burks@apachecor	rp.com PHONE:	432-556-9143		
For State Use Only			126 1240		
	-).	DATE	5120 2015		
Conditions of Approval (if any):					