

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-26752

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Maralo "16" State

8. Well Number 8

9. OGRID Number
281085

10. Pool name or Wildcat
Sioux Tansill (Yates 7 Rivers)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
RMR Operating, LLC

3. Address of Operator
14282 Gillis Rd. Farmers Branch, Texas 75244-3715

4. Well Location

Unit Letter K : 1980 feet from the South line and 1980 feet from the West line
Section 16 Township 26S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
2943'GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT

REMEDIAL WORK
COMMENCE DRILLING OPN INT TO PA Pm
CASING/CEMENT JOB P&A NR
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Pressure test casing to 500 psig

Circulate hole with 9.5# Brine w/ 12.5# gel/BBI

Spot 30 sxs on top CIBP at 3135', Spot 25 sxs at 2950'

Spot 25 sxs cmt @ 2045' WOC and Tag. Spot 25 sxs @ 1474' WOC and Tag. Spot 25 sxs @ 722' WOC and Tag.

Perf at 200' CIRC CMT TO SURFACE

Spot cmt plug from 200' to surface.

Perf at 722' SQZ w/ 50 sxs.

WOC & TAG AT 622' OR BETTER

verify cmt to surface all strings

Cut-off wellhead. Install marker. Clean Location

Spud Date:

Rig

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ross Pearson TITLE V.P. Operations DATE 4/3/18

Type or print name Ross Pearson E-mail address: ross@redmountainresources.com PHONE: 469-995-0425

For State Use Only

APPROVED BY: Manuel Dittler TITLE P.E.S. DATE 04/09/2018

Conditions of Approval (if any):

C103 INTENT TO P&A EXPIRES
1 YEAR FROM DATE OF APPROVAL

Maralo "16" State #8
 1980' FSL, 1980' FWL
 Section 16, T-26-S, R-36-E, Unit K Date: 02/08/201.
 Lea County, New Mexico
 API- 300-25-26752

WELLBORE DIAGRAM - NOT TO SCALE

