State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Saver

Deputy Cabinet Secretary

Heather Riley Division Director



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment" HOBBS OCD

APR 1 1 2018

RECEIVED

DIAMOND S ENERGY COMPANY

6608 Bryant Irvin Road Fort Worth TX 76132-6132

LETTER OF VIOLATION - Inspection

Dear Operator:

11-Apr-18

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

TEXACO SHELL STATE COM No.001

J-25-17S-34E

30-025-20948-00-00

Inspection

Date

Type Inspection

Inspector

Violation?

*Significant Non-Compliance? Corrective

Inspection No.

04/10/2018

Routine/Periodic

Mark Whitaker

Yes

No

Action Due By: 7/14/2018

iMAW1810125200

Violations

Absent Well Identification Signs (Rule 103)

Substandard Equipment and/or Needs Repai

Comments on Inspection:

Well sign not legible (Rule 19.15.16.8). No production reported in over 36 months (Rule 19.15.25.8). NEED TO REPLACE WELL SIGN. NEED TO RETURN WELL TO

PRODUCTION, REQUEST TA STATUS, OR PLUG & ABANDON. 1ST NOTICE

Rule 19.15.16.8 Sign should be legible from 50' and each sign shall show operator's name, property name, well number, location by footage, unit letter, section, township, range, and API number.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, Mahlwhitaku, P.E.S.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

HASLER
FIRST-CLASS MAIL
\$000.47⁰
04/11/2018 ZIP 88240
012E14642224

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

DIAMOND S ENERGY COMPANY 6608 BRYANT IRVIN ROAD FORT WORTH, TX 76132-6132