State of New Mexico Office District Dis					
Solition Content Con	Submit 3 Copies To Appropriate District State of New Me	exico	Form C-1	03	
Solition Content Con	District I			008	
Solition Content Con	1625 N. French Dr., Hobbs, NM 88240				
State Company Compan	1301 W. Grand Ave., Artesia, NM 8823 OU CONSERVATION DIVISION				
State Company Compan	District III 1000 Rio Brazos Rd., Aztec, NM 87410		STATE 🗸 FEE 🗌		
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR REMAIN" (FORM CHU) FOR SUCH RROPOSALS) 1. Type of Well: Oil Well	District IV				
DONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPERNOR PLUG BACK TO A DIFFERENT RESERVOIR. USE "PRICLATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027 3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027 4. Well Location Unit Letter	87505				
DIFFERENT RESERVOIR, USE "APPLICATION FOR PREMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name	е	
1. Type of Well: Oil Well	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO		CHRISTENSEN STATE		
2. Name of Operator 3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027 4. Well Location Unit Letter L 1980 feet from the SOUTH line and 660 feet from the WEST line Section 16 Township 11S Range 33E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF I PERFORM REMEDIAL WORK LEASHING DEVELOPED TO F: REMEDIAL WORK LEASHIN			8. Well Number 1		
3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027 4. Well Location Unit Letter L : 1980 feet from the SOUTH line and 660 feet from the WEST line Section 16 Township 115 Range 33E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF I PERFORM REMEDIAL WORK [INT TO PA P&A RR] PWA NR	2 Name of Operator		9. OGRID Number	-	
1.001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027 A. Well Location	JAY MANAGEMENT COMPANY, LLC		247692		
Well Location					
Unit Letter L. 1980 feet from the SOUTH line and 660 feet from the WEST line Section 16 Township 115 Range 33E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF I PERFORM REMEDIAL WORK [INT TO PA PARA PARA PARA PARA PARA PARA PARA		N,TX 77027	BAGLEY; PERMO PENN, NORTH	1	
Section 16 Township 11S Range 33E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF I PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [P&A NR [PULL OR ALTER CASING [PAND A [COMMENCE DRILLING OPNS [PAND A [CASING/CEMENT JOB [PAND A [CASING/CEMENT JOB [PAND A [COMMENCE DRILLING OPNS [PAND A [CASING/CEMENT JOB] OTHER: OTH	1000	1 11 1 6	SEO C. C. A. WEST II		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF I PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [P&A NR PULL OR ALTER CASING [P&A NR POWNHOLE COMMINGLE [P&A R OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE I 103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/21/2018 : Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 8250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. 03/21/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590' perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/27/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 Type or print name Clay Grifin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691	Offic Letter lect from the			1e	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF PERFORM REMEDIAL WORK INT TO PA PERFORM REMEDIAL WORK INT TO PA P&A NR P&A NR INT TO PA P&A NR PAND A INT TO PA PAND A INT TO	110				
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE P&A R OTHER:		1110, 117, 014, 010.)			
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE P&A R OTHER:					
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON P&A NR P&A NR DOWNHOLE COMMINGLE P&A R OTHER: OT	Check Appropriate Box to Indicate N	ature of Notice,	Report or Other Data		
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON P&A NR P&A NR DOWNHOLE COMMINGLE P&A R OTHER: OT	NOTICE OF I	SUB	SECUENT REPORT OF:		
P&A NR OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for Instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt. (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/23/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 2400' attempted to squeeze. Squeeze 80 sx c	PERFORM REMEDIAL WORK [
DOWNHOLE COMMINGLE [P&A R] OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/2/1/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt. (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691	TEMPORARIET ABANDON		ILLING OPNS. P AND A		
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt. (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 For State Use Only APPROVED BY: New York.		CASING/CEMENT	T JOB		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE I103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 1590' Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 2150'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: Cgriffin@jaymgt.com PHONE: 574-707-5691 PAPROVED BY: Xewy 3vt. 2019	DOWNHOLE COMMINGLE P&A R		1		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 TITLE	OTHER:	OTHER:	1		
or recompletion. 03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction. Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Spud Date: 03/17/2018 Rig Release I Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 PAPROVED BY: Yeury Juther TITLE Complaine Office A Botton Date 4-17-78	13. Describe proposed or completed operations. (Clearly state all p	pertinent details, and	give pertinent dates, including estimated	date	
Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'. 03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 2400'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: Cgriffin@jaymgt.com PHONE: 574-707-5691 PHONE: 574-707-5691					
03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction. Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. Tag at 3590'. Perforate at 2400'. Tag at 2150'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: Cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Complaince Office	03/21/2018: Attempted to Set CIBP at 8618'. Call OCD for instruction.				
Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'. 03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt. (Per Mark w/OCD). Tag at 2150'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Office Complined Compliance Office Compliance Office Compliance Office Complia	Set CIBP at 8443' and pump 25 sx class H cmt (Per Kerry w/OCD). Tag at 8090'.				
03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for instruction. Pump balance plug at 2450' with 25 sx class C cmt (Per Mark w/OCD). Tag at 2150'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Sriffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Official DATE 4-17-/8	03/22/2018: Perforate at 6200' attempted to squeeze. Call OCD for instruction.				
instruction. Pump balance plug at 2450' with 25 sx class C cmt (Per Mark w/OCD). Tag at 2150'. 03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'.Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 SIGNATURE TITLE District Manager DATE 04/16/2018 E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Office use DATE 4-17-/8	Pump balance plug at 6250' with 20 sx class C cmt (Per Mark w/OCD). Tag at 5950'.				
03/24/2018: Perforate at 1700'. Squeeze 60 sx class C cmt. Tag at 1590'. Perforate at 375'. Squeeze 80 sx class C cmt. Tag at 240'. 03/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. 04/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03 - 25 - 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Officer DATE 4-17-/8	03/23/2018: Perforate at 3800'. Squeeze 30 sx class C cmt. Tag at 3590'. Perforate at 2400' attempted to squeeze. Call OCD for				
O3/25/2018: Perforate at 100'. Squeeze 60 sx class C cmt. Circulate cmt to surface. O4/10/2018: Cut off wellhead 3' below ground level and install upright P&A marker. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Officer DATE 4-17-/8	instruction. Pump balance plug at 2450' with 25 sx class C cmt (Per Mark w/OCD). Tag at 2150'.				
Spud Date: O3/17/2018 Rig Release I Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By O3 - Z5 - Z019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 For State Use Only APPROVED BY: Keyy Futher TITLE Complance Officer DATE 4-17-/8					
Spud Date: 03/17/2018 Rig Release I Rig Release I Rig Release I Rig Release I Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03- 25- 2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 For State Use Only APPROVED BY: Yeary Further TITLE Compliance Officer DATE 4-17-/8					
Spud Date: 03/17/2018 Rig Release I under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 For State Use Only APPROVED BY: Restoration Due By DATE 4-17-/8	04/10/2018 : Cut off wellhead 3' below ground level and install u	pright P&A marker.			
Rig Release I completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 APPROVED BY: Restoration of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms. Restoration Due By 03-25-2019 DATE 04/16/2018 Title Compliance Officer DATE 4-17-/8		Approved for I	Plugging of wellbore only. Liability		
SIGNATURE TITLE District Manager E-mail address: cgriffin@jaymgt.com DATE 04/16/2018 TITLE Compliance Officer DATE 4-17-/8	Snud Date: 03/17/2018 Pig Palages F				
TITLE District Manager TITLE District Manager DATE 04/16/2018 E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Officer DATE 4-17-/8	Spud Date. US/11/2018 Rig Release L				
SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 TITLE Compliance Officer DATE 4-17-/8					
SIGNATURE TITLE District Manager DATE 04/16/2018 Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 APPROVED BY: Remy Futher TITLE Compliance Officer DATE 4-17-18	I hereby certify that the information above is true and complete to the l	Restoration Di	ue By 03-25-2019		
Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 APPROVED BY: Yeary Futher TITLE Compliance Officer DATE 4-17-18	11 11 .				
Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691 APPROVED BY: Yeary Futher TITLE Compliance Officer DATE 4-17-18	SIGNATURE / VOM MA TITLE DIVI		DATE:		
APPROVED BY: Kerry Further TITLE Compliance Officer DATE 4-17-18	SIGNATURE District	ot Manager	DATE 04/16/2018		
APPROVED BY: Kerry Further TITLE Compliance Officer DATE 4-17-18	Type or print name Clay Griffin E-mail address	: cgriffin@jaymqt	t.com PHONE: 574-707-5691		
	APPROVED BY: Yours Just a	0.2	DATE 4-12-10		
		euro offic	DATE 7-1/18		