Office	State of New Mexico	Form C-103
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240BBS OCT	Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
		3002528057
811 S. First St., Artesia, NM 88210 District III – (5075) 748-1283 APR 01 20181220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fo NIM 87505		STATE XX FEE
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NNRECEIVED	Salita Pe, INIVI 67505	6. State Oil & Gas Lease No.
87505		3
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name State 35 Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		8. Well Number
PROPOSALS.) 1. Type of Well: Oil Well Gas Well xx Other WIW		014
2. Name of Operator		9. OGRID Number
McGowan Working Partners Inc.		220397
3. Address of Operator		10. Pool name or Wildcat
PO Box 55809 Jackson MS 39296-5809		Vacuum GB/SA
4. Well Location		
Unit Letter_K :_2630feet from the _south line and1330feet from the		
westline		
Section 35	Township 17 south Range	34 east NMPM
County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Elevation (Snow whether DR, RRB, R1, OR, etc.)		
Characteristics and calcular properties of a particular memorital properties of the Administration of the Admi		Approximately, these and december of a manufacture of the second
12. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK xx PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE		RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE		
DOWNHOLE COMMINGLE		_
CLOSED-LOOP SYSTEM	07.150	
OTHER:	OTHER:	ad give partinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Pull tubing find hole in tubing replace joint with new tubing run back in hole set packer back within 100 ft. of perforation and hang well on. Do MIT put well back on production.		
on. Do Will put well back on production.		
	Condition	on of Approval: notify
OCD Hobbs office 24 hours		Labba office 24 hours
	prior of ru	inning MIT Test & Chart
		The state of the s
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true	and complete to the best of my knowled	ge and belief.
SIGNATURE JAAR	TITLE Pan Par	DATE 41-2-2018
SIGNATURE DATE OF THE		
Type or print name Sack STEVENSON E-mail address: Jck OTWT By Q Hot MAIL PHONE: 575-631-1083		
TITLE FUNTER DATE 4-2-2018 Type or print name Speck Stevenson E-mail address: Jekasutr By @ Kot M+1/PHONE: 575-631-1083 For State Use Only		
APPROVED BY: Notey STOWNITLE AO II DATE 4/2/2018		
Conditions of Approval (if any):		