UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT'S DAO FIELD OFFICE

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

B	LIDEVILLE LYMD MYNYV	TEVIEWILLOSS, EMPREN	题 图 4017777000	LAPITOS. 5	unual y 51, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				5. Lease Serial No. NMNM053434		
				6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 3 BBS OCD				7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other,			PR 2 4 2018	8. Well Name and No. LEA UNIT 2		
Name of Operator Contact: D. PATRICK LEGACY RESERVES OPERATING LPE-Mail: pdarden@legacylp.com			FCEIVE	9. API Well No. 30-025-02428		
3a. Address 303 W WALL ST STE 1800 MIDLAND, TX 79701		3b. Phone No. (include sits code) Ph: 432-689-5200 Ext: 5237		101 11010 0110 1 001 01	10. Field and Pool or Exploratory Area LEA; DEVONIAN	
4. Location of Well (Footage, Sec., 7				11. County or Parish, State		
Sec 12 T20S R34E SENW 1950FNL 1950FWL				LEA COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	ΓΟ INDICATE NAT	JRE OF NOT	ICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
■ Notice of Intent	☐ Acidize	☐ Deepen	□ Pro	oduction (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Frac	cturing	clamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construc	tion 🛭 Re	complete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abar	don			
	☐ Convert to Injection	☐ Plug Back	ck			
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for the Legacy Reserves will be recoformation. An earlier Sundry frequest. Legacy's planned pro	ork will be performed or provide in dispersions. If the operation residend bandonment Notices must be file final inspection. If the operation will be file final inspection. If the operation will be file final inspection.	he Bond No. on file with E ults in a multiple completic d only after all requiremen phole by opening pay in to P&A the well, ple	LM/BIA. Requir n or recompletion is, including reclar in the Bone Si	ed subsequent reports must be in a new interval, a Form 31 mation, have been completed	e filed within 30 days 60-4 must be filed once	
- Attempt to get passed collap - If successful set CIBP @~12 - If successful set CIBP @~12 - If not successful set CIBP as - Set CIBP @~12,300' w/50' of - Add Bone Spring pay from a - Return well to production.	3,840' w/50' cmt on top. 2,850' w/50' cmt on top. s deep as possible w/50' cr cmt on top.	mt on top. SEE CON		HED FOR S OF APPROV	AHON TO HEO PREDER	
14. I hereby certify that the foregoing is	Electronic Submission #4	ERVES OPERATING LI	LM Well Inform P. sent to the H	ation System		
Name (Printed/Typed) D. PATRICK DARDEN, PE				RING ADVISOR		
Signature (Electronic	Submission)	Date (03/27/2018			
	THIS SPACE FO	R FEDERAL OR S	TATE OFFIC	E USE		
Approved By	Haque_	Title	Engineer		Date 64-18-2018	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condi-	uitable title to those rights in the		CFO			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)


** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **




Additional data for EC transaction #409435 that would not fit on the form

32. Additional remarks, continued

Wellbore diagram attached.



PROPOSED WELLBORE DIAGRAM



brumation Tops: Bone Sprang=8150' 133/8" @ 851 Wolf comp = 11,003' morrow = 12,710' DU Tool @ 3417' Devonian = 14,365' 75/8 @ 5006' + TOC @ 8000° Bone Spreng pends: 8700-9580 (Added) Existing Bone Spring pents: 9590-9645' 1 ON TOOL @ 105941 Spot class H cement from 10644'- 10544 (DV Tool plug) D Spot class H cerrent from 11053'-10843'.
woc & Toy Cwolfcomp Plus) PCIBP @ 12760' with 25 nacks of class H cement on top. woc & Tog (monnow Play monrow: 12874'-912', 13:46'-156' .pot class 4 cement from 14054'-13954' 4 14 1/2" Dia C 14,0064' liner top plug) 34 @ 17/00. D Spot class H cement from 14415'-1405 woc & Tay. (Devonion Plug) & 7" shoe # Dermia 14387 - 414, 14431 - 461 Th: 14,501 PB10: 14,476'

Lea Unit 2 30-025-02428 Conditions of Approval

Notify BLM at 575-361-2822 (Eddy County) or 575-393-3612 (Lea County) a minimum of 24 hours prior to commencing work.

Work to be completed by July 18, 2018.

Following plugging procedure needs to be completed before proceeding to Bone Spring recompletion operation:

- i. Model D packer at 13,860' needs to be pulled out.
- ii. Spot class H cement from 14,415' 14,050'. WOC and Tag.
- iii. Spot class H cement from 14,054' 13,954'.
- iv. Set CIBP at 12,760' with 25 sacks of class H cement on top. WOC and Tag.
- v. Spot class H cement from 11,053' 10,843'. WOC and Tag.
- vi. Spot class H cement from 10,644' 10,544'.
- 1. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.

- 7. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 9. See attached for General Plugback Guidelines

MHH 04182018

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date</u> <u>work was completed.</u> If plugging back to a new zone submit a Completion Report, form 3160-4

with the Subsequent Report.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.