Submit 1 Co	ppy To Appropriate District	State of New Mexico		Form C-103				
	(575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.				
District II –	nch Dr., Hobbs, NM 88240 (575) 748-1283	ONI CONCEDIATION	N DIVICION	30-025-26776				
811 S. First District III -	11 – (575) 393-6161 I. French Dr., Hobbs, NM 88240 11 – (575) 748-1283 First St., Artesia, NM 88210 11 – (505) 334-6178 io Brazos Rd., Aztec, NM 87505 Santa Fe, NM 87505			5. Indicate Type of Lease				
1000 Rio Bi	razos Rd., Aztec, NM 87410	Santa Fe NM S	27505	STATE X	FEE			
1220 S. St. 1	- (505) 334-6178 razos Rd., Aztec, NM 87410 - (505) 476-3460 Francis Dr., Santa Fe, NM APR SUNDRY NOTICE	Santa I C, IVIVI C	57303	6. State Oil & Gas Lo	ease No.			
87505	Francis Dr., Santa Fe, NM		* A					
(DO NOT U	ISE THIS FORM FOR PROPOSA T RESERVOIR. USE "APPLICA"	7. Lease Name or Unit Agreement Name EAST VACUUM GB-SA UNIT TRACT 2720						
PROPOSAL 1. Type of	-,	as Well Other		8. Well Number 007				
	Name of Operator ConocoPhillips Company				9. OGRID Number			
3 Address		217817 10. Pool name or Wildcat						
3. Addres	ss of Operator P. O. Box 518 Midland, TX	VACUUM; GB-SA						
4. Well L				VACCOM, GB-SA				
J	Jnit Letter H : 24	50 feet from the NORTH	l line and 150	feet from th	ne EAST line			
S	Section 27	Township 17S R	lange 35E	NMPM Co	ounty LEA			
		11. Elevation (Show whether DI	R, RKB, RT, GR, etc.)					
	12 Check An	propriate Box to Indicate N	Nature of Notice	Report or Other Da	ta			
	12. Check Ap	propriate box to fidicate i	value of Notice,	Report of Other Da	ıa			
	NOTICE OF INT			SEQUENT REPO				
		PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK		TERING CASING AND A			
		MULTIPLE COMPL	CASING/CEMENT		IND A			
	DLE COMMINGLE	WOETH EE OOM E	O/ (OII TO/OEMEIT					
OTUED, 1	DEMONE FOLUD & CET C	IDD WIGHT	OTHER.					
OTHER: REMOVE EQUIP & SET CIBP W/CMT								
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or recompletion.								
CONOCOPHILLIPS COMPANY WOULD LIKE TO PERFORM EQUIP REMOVAL AND SET CIBP W/CMT PER ATTACHED								
PROCEDURE ATTACHED IS CURRENT/PROPOSED WELLBORE SCHEMATIC								
Spud Date:		Rig Release D	ate:					
T.1 1				11 1' 0				
I hereby cer	tify that the information abo	ove is true and complete to the b	est of my knowledge	e and belief.				
SIGNATURE DATE 04/24/2018 TITLE Staff Regulatory Technician DATE 04/24/2018								
Type or pri	nt name Rhonda Rogers	F-mail address	s: rogerrs@conocor	hillins com PHONI	E: <u>(432)688-9174</u>			
Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: (432)688-9174 For State Use Only								
5/7/7018								
APPROVED BY: DATE DATE DATE								
Conditions	or reperoral (it ally)		•					

Project Scope

Justification and Background: Pull ESP, set plug, and cement

This well has been submitted for P&A. This procedure will serve to pull the ESP that is currently downhole and set a cast-iron bridge plug to secure the wellbore until Basic Energy Services is available to plug the well.

Wellbore Info						
Type	Formation	Top	Bottom			
Perforations	Grayburg / San Andres	4,351'	4,665'			
PBTD	4,740'					
TD	4,800'					

Well Service Procedure:

- 1) MIRU WSU. Kill well.
- 2) NDWH, NUBOP. RU cable and CT spoolers. POOH tubing with ESP assembly. LD ESP and stand back tubing. RD spooler.
- 3) PU & RIH w/bit & scraper for 7" 23# casing. Clean out just passed plug set depth @ 4300'. POOH and LD all.
- 4) PU MIRU wireline services. PU CIBP for 7" casing, setting tool, & CCL. RIH & set CIBP @ ~4300' (avoiding collars). POOH& LD CCL & setting tool.

> PU cement bailer. RIH & dump bail 20 of cement on top of CIBP. POOH, RDMO wireline services.

6) NDBOP, NUWH. RDMO WSU. Clean location.

CMT TO BE PLACED BY BASIC WHEN P/A STARTS.

WHEN P/A

Proposed Tubing Configuration EAST VACUUM GB-SA UNIT 2720-007 300252677600

