

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

Ken McQueen  
Cabinet Secretary

Matthias Sayer  
Deputy Cabinet Secretary

Heather Riley  
Division Director



**\*Response Required - Deadline Enclosed\***

*Underground Injection Control Program*

*"Protecting Our Underground Sources of Drinking Water"*

**HOBBS OCD**

**MAY 02 2018**

**RECEIVED**

02-May-18

**BTA OIL PRODUCERS, LLC**  
104 S. Pecos  
Midland TX 79701-9701

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE**  
**Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

**MECHANICAL INTEGRITY TEST DETAIL SECTION**

|                            |                                 |   |
|----------------------------|---------------------------------|---|
| <b>BUCKEYE 8601 No.002</b> | Active Salt Water Disposal Well | <b>30-025-28433-00-00</b><br>E-29-17S-36E |
|----------------------------|---------------------------------|---|

|   |                                   |                      |
|---|-----------------------------------|----------------------|
| Test Date: 5/1/2018   | Permitted Injection PSI:          | Actual PSI:          |
| Test Reason: Annual IMIT  | Test Result: F                    | Repair Due: 8/4/2018 |
| Test Type: Bradenhead Test  | FAIL TYPE: Other Internal Failure | FAIL CAUSE:          |
| Comments on MIT: BHT-FAILED, RULE: 19.15.26.11, PROD CSG & TBG WERE ON STRONG VACUUM, WELL STILL SHUT IN FROM FAILED BHT LAST YEAR. **SECOND NOTICE** |                                   |                      |

|                             |   |  |
|-----------------------------|---|--|
| <b>MESA B SWD 8115 JV-P</b> | No.002<br>Active Salt Water Disposal Well | <b>30-025-42462-00-00</b><br>P-7-26S-33E |
|-----------------------------|---|--|

|  |                                   |                      |
|--|-----------------------------------|----------------------|
| Test Date: 5/1/2018  | Permitted Injection PSI:          | Actual PSI:          |
| Test Reason: Annual IMIT   | Test Result: F                    | Repair Due: 8/4/2018 |
| Test Type: Bradenhead Test   | FAIL TYPE: Other Internal Failure | FAIL CAUSE:          |
| Comments on MIT: FAILED BHT, RULE: 19.15.26.11, PROD CSG HAD 700 PSI, BLEW PRES & FLUID DOWN TO 200 PSI & WOULD NOT STOP -- SHUT PROD CSG & PRES BUILT BACK UP TO 700 PSI. SHUT WELL IN. |                                   |                      |

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, 

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240

BTA OIL PRODUCERS, LLC  
104 S PECOS  
MIDLAND, TX 79701-9701



HASLER

FIRST-CLASS MAIL

**\$000.47<sup>0</sup>**

05/02/2018 ZIP 88240  
012E14642224

US POSTAGE