Submit 1 Copy To Appropriate District	State of NI-res Marches	F
Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District 1</u> – (373) 393-6161 1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-25-44288
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	QIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 (0 South St. Francis Dr.	STATE FEE X
<u>District IV</u> – (505) 476-3460	Energy, Minerals and Natural Resources NUL CONSERVATION DIVISION CONSERVATION DIVISION South St. Francis Dr. Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505) 	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PRODUCTS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Libby Berry Fee SWD
1. Type of Well: Oil Well Gas Well Other SWD		8. Well Number 1
2. Name of Operator 3Bear Field Services, LLC		9. OGRID Number 372603
3. Address of Operator 500 Don Gaspar, NE		10. Pool name or Wildcat
Santa Fe, NM 87505		SWD; Miss-Devonian
4. Well Location	510 feet from the North line and 7	10 feet from the East line
Unit Letter H : 2 Section 26	510 feet from the <u>North</u> line and <u>7</u> Township 20S Range 34E	ID feet from the East line NMPM Lea County Image: County
Section 20 Range 512 Reference 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation 11. Elevation		
3620 GL		
12 Charle Am	manufata Day to Indicate Nature of Nation	Panast or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A		
—	MULTIPLE COMPL CASING/CEMEN	
CLOSED-LOOP SYSTEM		TD and Rig Release 🛛 🗶
13. Describe proposed or complet	ed operations. (Clearly state all pertinent details, an	
of starting any proposed work proposed completion or recom). SEE RULE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
proposed completion of recon	proton.	
WOC and NUBOP. Drill out float collar and test casing to 1000 psi 30 min OK. Drill out shoe and commence drilling 6" hole @ 11:30		
pm 5/18/18.		
Drill 6" hole to 16,000', TD @ 4;30 am 5/21/2018. Log hole w/ CNL Z-Densitlog and Rt Explorer Micro-Laterolog		
	- D. J	
	tion Packer and 281 jts 4.5" 12.75# P110 CS Hydrill est to 1200 psi Good. Disconnect from On-Off tool a	
back on to on-off tool.		
Release rig @ 6:00 pm 5/23/2018	» .	
Release fig (0.00 pin 5/25/2018		
Spud Date: March 23, 2018	Rig Release Date: 5/23/201	.8
I hereby certify that the information abo	ove is true and complete to the best of my knowledg	e and belief.
\sim		
SIGNATURE	TITLE Consultant	DATE 6/7/18
Dhalma White		575 676 7660
Type or print name Phelps White	E-mail address:pwiv@zianet.	PHONE:
For State Use Only Way House AOUT 111/2010		
	MK ///	111000
APPROVED BY: Conditions of Approval (if any):	Brown TITLE AO/II	DATE 6/11/2018